

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 13 Jul 2022

Preliminary Advice

Insured Vehicle No	: SLB5343A	Accident Date	: 09/04/2022
TP Vehicle No	: SMG2522G	Assignment Date	: 12/04/2022
Make	: HONDA FIT	Est. Duration of Repair	: 3
Date of Inspection	: 16/06/2022		
Inspection At	: MODERN AUTOMOTIVE PTE LTD (HQ) BLK 3023A UBI ROAD 1, #01-61 & #01-58 SINGAPORE 408717		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,992.92
Revised Amount	:S\$	2,247.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,247.64

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.