

Kang Car Repairers Pte Ltd

408, Box 12, Singapore 477102
 Email: kangcar@singnet.com.sg

M/S: SMRT BUSES LTD
 6 ANG MO KIO ST 62
 SINGAPORE 569140

ATTN: Motor Claim Department

Claim Type: Third Party
 Accident Date: 05-04-2022
 TP Veh Reg No: SG1699R

Estimate No: EST2200103
 Date: 09 Apr 2022
 Veh Reg No: SKK808Z
 Make/Model: TOYOTA LEXUS
 AERAS 2.3
 Chassis No: AEP50700
 Reg. Date: 22-12-2008
 Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BOOT LID <i>Distorted</i>		
2	2 PCS BOOT LID HINGE <i>new</i>		
3	2 PCS BOOT LID SHOCK ABSORBER <i>new</i>		
4	1 PC BOOT LID RUBBER <i>cut</i>		
5	1 PC BOOT LID LOGO		
6	1 PC BOOTLID "ESTIMA" EMBLEM <i>3 new</i>		
7	1 PC BOOTLID "AERAS" EMBLEM		
8	1 PC BOOT LID LAMP LH <i>3 smashed</i>		
9	1 PC BOOT LID LAMP RH		
10	1 PC BOOTLID REFLECTOR LAMP <i>smashed</i>		
11	1 PC BOOT LID CHROME <i>cracked</i>		
12	2 PCS REAR NUMBER PLATE LAMP <i>cracked</i>		
13	1 PC BOOTLID AUTO LOCK <i>new</i>		
14	1 PC BOOTLID AUTO LOCK BUTTON <i>new</i>		
15	1 PC BOOTLID LOCK <i>new</i>		
16	1 PC BOOTLID LOCK COVER <i>new</i>		
17	1 PC BOOT LID LOCK CHECKER <i>new</i>		
18	2 PCS BOOT LID TOP CORNER RUBBER <i>new</i>		
19	1 PC BOOTLID RH SIDE STOPPER <i>new</i>		
20	1 PC BOOTLID LH SIDE STOPPER		
21	1 PC BOOT LID TRIM <i>del</i>		
22	2 PCS BOOTLID TRIM SIDE SMALL COVER <i>del</i>		
23	1 PC BOOT LID OUTER OPENER HANDLE <i>new</i>		
24	1 PC REAR WIPER MOTOR <i>new</i>		
25	1 PC REAR WIPER ARM <i>new</i>		
26	1 PC REAR WIPER BLADE <i>new</i>		
27	1 PC REAR WINDSCREEN GLASS <i>shattered</i>		
28	2 PCS REAR WINDSCREEN INNER SIDE TRIM <i>cut</i>		
29	1 PC REAR WINDSCREEN RUBBER <i>new</i>		

Kang Car Repairers Pte Ltd

100-101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

M/S: SMRT BUSES LTD
6 ANG MO KIO ST 62
SINGAPORE 580140

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make Model: TOYOTA YARIS
AERAS 2.0 V X
Chassis No: ACRES0078336
Reg Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR WINDSCREEN TOP TRIM <i>seen</i>		
31	1 PC REAR BOOTLID SPOILER <i>seen</i>		
32	1 PC REAR BOOTLID HOLDER COVER <i>Missing</i>		
33	1 PC REAR FENDER RH <i>Brickd</i>		
34	1 PC REAR FENDER GLASS RH <i>seen</i> with rubber		
35	1 PC REAR RH SLIDING DOOR RAIL <i>seen</i>		
36	1 PC REAR FENDER INNER TRIM RH <i>Brickd</i>		
37	1 PC REAR FENDER TOP TRIM RH <i>Brickd</i>		
38	1 PC REAR FENDER COWLING RH <i>seen</i>		
39	1 PC AIR CON BLOWER MOTOR <i>seen</i>		
40	1 UNIT REAR SEAT BELT RH <i>seen</i>		
41	1 PC REAR SEAT BELT COVER RH <i>Brickd</i>		
42	1 PC REAR SEAT BELT LH <i>Brickd</i>		
43	1 PC REAR SEAT BELT COVER LH <i>Brickd</i>		
44	1 PC REAR FENDER LH <i>Brickd</i>		
45	1 PC REAR FENDER GLASS LH <i>shattered</i>		
46	1 PC REAR LH SLIDING DOOR RAIL <i>seen</i>		
47	1 PC REAR LH FENDER INNER TRIM <i>Brickd</i>		
48	1 PC REAR FENDER TOP TRIM LH <i>Brickd</i>		
49	1 PC REAR SPARE TOOL BRACKET LH <i>seen</i>		
50	1 PC REAR SPARE TYRE JACK BRACKET LH <i>Brickd</i>		
51	1 PC REAR LH FENDER COWLING <i>seen</i>		
52	1 PC REAR LH FENDER JACK OUTER COVER <i>Brickd</i>		
53	1 PC TAIL LAMP - RH <i>Smashed</i>		
54	1 PC TAIL LAMP PILLAR RH <i>Brickd</i>		
55	1 PC TAIL LAMP LH <i>Smashed</i>		
56	1 PC TAIL LAMP PILLAR LH <i>Brickd</i>		
57	1 PC REAR PANEL <i>Brickd</i>		
58	1 PC REAR PANEL TRIM <i>Brickd</i>		
59	1 PC REAR PANEL BOTTOM TRIM <i>Brickd</i>		
60	1 PC REAR BOOT HARD COVER		

Kang Car Repairers Pte Ltd

100-110, Block 10, Singapore 110001
Tel: 6747 1111 Fax: 6747 1112 Email: kangcar@singnet.com.sg

MS: SMRT BUSES LTD
6 ANG MO KIO ST 62
SINGAPORE 359449

ATTN: Motor Claims Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4V SR
Chassis No: ACX5007500
Reg. Date: 22/12/2003
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No: SKK808Z

Quantity	Description	List Price	Amount
		SS	SS
61	1 PC SPARE TYRE PANEL <i>Repair</i>		
62	1 PC SPARE TYRE TRIM <i>new</i>		
63	1 PC REAR BUMPER <i>Rebuild</i>		
64	2 PCS REAR BUMPER SPONGE <i>included</i>		
65	2 PCS REAR BUMPER SCREW COVER <i>missing</i>		
66	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>		
67	2 PCS REAR BUMPER SMALL RETAINER <i>new</i>		
68	2 PCS REAR BUMPER BRACKET <i>Rebuild</i>		
69	2 PCS REAR TOWING COVER <i>Rebuild</i>		
70	2 PCS REAR BUMPER REFLECTOR <i>included</i>		
71	1 PC REAR BUMPER MUDFLAP RH <i>new</i>		
72	1 PC REAR CIGARETTE LIGHT SWITCH <i>2 Pin Bond</i>		
73	1 PC REAR CIGARETTE LIGHT SWITCH COVER <i>Rebuild</i>		
74	1 PC EXHAUST PIPE <i>new</i>		
75	1 PC BONNET <i>Dented</i>		
76	2 PCS BONNET HINGE <i>new bent</i>		
77	1 PC BONNET RUBBER <i>new</i>		
78	1 PC BONNET LOCK <i>Dented</i>		
79	1 PC BONNET LOCK CABLE <i>new</i>		
80	1 PC FRT BRACE PANEL <i>new</i>		
81	1 PC FRT BUMPER <i>Rebuild</i>		
82	1 PC FRT BUMPER SPONGE <i>new included</i>		
83	1 PC FRT BUMPER REINFORCEMENT <i>Bent</i>		
84	1 PC FRT BUMPER TOP BEAM <i>Bent</i>		
85	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>		
86	1 PC FRT BUMPER GRILLE <i>Rebuild</i>		
87	2 PCS FRT BUMPER BRACKET <i>new</i>		
88	1 PC FRT FOG LAMP RH <i>Rebuild</i>		
89	1 PC FRT FOG LAMP LH <i>Rebuild</i>		
90	2 PCS FRT TOWING COVER <i>Rebuild</i>		
91	1 PC HEADLAMP LH <i>Rebuild</i>		

[illegible]

ATTN: Major Client Department

Estimate No:	EST2200103
Date:	09 Apr 2002
Van Reg No:	SKK808Z
Make Model:	TOYOTA ESTIMA AERAS 2.0A
Chassis No:	ACR30067806
Reg. Date:	22/12/2003
Your Ref No:	SG1699R

Claim Type:	Third Party
Accident Date:	05/04/2022
TP Veh Reg No:	SG1699R

Quantity	Description	List Price	Amount
92	1 PC HEADLAMP RH <i>cracked</i>	<u>SS</u>	<u>SS</u>
93	1 PC FRT SUPPORT PANEL <i>Bushed</i>		
94	1 PC FRT SUPPORT PANEL TOP TRIM <i>del</i>		
95	1 PC FRT FENDER COWLING RH <i>torn</i>		
96	1 PC FRT FENDER COWLING LH <i>torn</i>		
97	1 PC FRT GRILLE <i>cracked</i>		
98	1 PC FRT GRILLE EMBLEM <i>new</i>		
99	1 PC FRT GRILLE RUBBER <i>new</i>		
100	1 PC RADIATOR <i>Distorted</i>		
101	2 PCS RADIATOR TOP BRACKET <i>gnt</i>		
102	2 PCS RADIATOR TOP BUZZ <i>Brush new</i>		
103	2 PCS RADIATOR BOTTOM BUZZ <i>new</i>		
104	1 PC RADIATOR TOP GARNISH <i>cracked</i>		
105	1 PC RADIATOR UNDER COVER <i>torn</i>		
106	1 PC RADIATOR FAN <i>cut Bent</i>		
107	1 PC RADIATOR FAN MOTOR <i>and</i>		
108	1 PC RADIATOR FAN COWLING <i>cracked</i>		
109	1 PC AIRCON CONDENSER <i>Distorted</i>		
110	1 PC AIR CON FAN <i>cut</i>		
111	1 PC AIRCON FAN MOTOR <i>and</i>		
112	1 PC AIRCON DISCHARGE PIPE <i>Bent</i>		
113	1 PC AIRCON RECEIVER PIPE <i>Bent</i>		
114	1 PC AIRCON LIQUID PIPE <i>torn</i>		
115	1 PC AIRCON SUCTION HOSE <i>new</i>		
116	2 PCS AIR CONDENSER BOTTOM BUZZ <i>Brush new</i>		
117	2 PCS AIR CONDENSER SIDE GARNISH <i>del</i>		
118	2 PCS AIR CONDENSER TOP BUZZ <i>Brush new</i>		
119	2 PCS HORN <i>and</i>		
120	1 PC FRONT WIPER WATER TANK <i>new</i>		
121	1 PC FRONT WIPER WATER TANK MOTOR <i>new</i>		
122	1 PC AIR CLEANER OUTLET AIR DUCT <i>del</i>		

Kang Car Repairers Pte Ltd

1 Kaki Bukit Road 2, #01-01, Singapore 417883
Tel: 6747 7500 Fax: 6747 7501 Email: kangcar@singnet.com.sg
GST: 1000000000

MLS: SMRT BUSES LTD
6 ANG MO KIO ST 62
SINGAPORE 369140

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA BUSTIMEX
AERAS 2.4A SR
Chassis No: ACR500078
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No: SKK808Z

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
123	1 PC FRT ISOLATOR BOX <i>new</i>		
124	1 PC FRT EXHAUST CATALYTIC CONVERTER <i>3rd</i>		
125	1 PC FRT EXHAUST CATALYTIC CONVERTER COVER <i>new</i>		
2 PC	Fog Lamp Cover <i>new</i>		
	<i>Special Net</i>		
126	1 SET BOOTLIDREFLECTOR LAMP CLIPS <i>new</i>		
127	1 PC REAR NUMBER PLATE <i>3rd</i>		
128	1 SET BOOT LID TRIM CLIPS <i>new</i>		
129	1 PC REAR WINDSCREEN SEAL <i>3rd</i>		
130	1 PC REAR WINDSCREEN SEALANT <i>new</i>		
131	1 PC REVERSE CAMERA <i>new</i>		
132	1 PC REVERSE VIEW CAMERA <i>Missing</i>		
133	1 SET REAR WINDSCREEN INNER SIDE TRIM CLIPS <i>new</i>		
134	1 SET REAR WINDSCREEN TOP TRIM CLIPS <i>new</i>		
135	1 PC REAR FENDER GLASS SEALANT RH <i>3rd</i>		
136	1 PC REAR FENDER GLASS SEAL RH		
137	1 SET REAR FENDER INNER TRIM RH CLIPS <i>new</i>		
138	1 SET REAR FENDER TOP TRIM RH CLIPS <i>new</i>		
139	1 SET REAR FENDER COWLING CLIPS RH <i>new</i>		
140	1 PC REAR FENDER GLASS SEAL LH <i>3rd</i>		
141	1 PC REAR FENDER GLASS LH SEALANT <i>new</i>		
142	1 SET REAR FENDER INNER TRIM CLIPS <i>new</i>		
143	1 SET REAR FENDER TOP TRIM CLIPS LH <i>new</i>		
144	1 SET REAR FENDER COWLING CLIPS LH <i>new</i>		
145	1 SET REAR PANEL TRIM CLIPS <i>new</i>		
146	1 SET REAR BUMPER CLIPS <i>new</i>		
147	1 SET REVERSE SENSORS <i>new</i>		
148	1 SET REAR BUMPER MUDFLAP CLIPS RH <i>new</i>		
149	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>		

Less 25%

1. Kalk, B. & C. (1998) *Handbook of Singapore Birds*. Singapore: Singapore Bird Club.
 2. Pielou, E. C. (1975) *Mathematical Ecology*. New York: Wiley.
 3. Pielou, E. C. (1977) *Mathematical Ecology*. New York: Wiley.

Estimate No:	EST2200103
Date	09 Apr 2022
Veh Reg No	SKK808Z
Make Model	TOYOTA AERAS 2.4 V 80
Chassis No	ACR50017000
Reg. Date	22/12/2003
Your Ref No:	SG1699R

Quantity	Description	List Price	Amount
150	1 PC FRT NUMBER PLATE Bent	50.00	30
151	1 SET FRT BUMPER CLIPS	100.00	50
152	1 SET FRT SUPPORT PANEL TOP TRIM CLIPS	80.00	X
153	1 SET FRT FENDER COWLING CLIPS RH	120.00	✓
154	1 SET FRT FENDER COWLING CLIPS LH	80.00	50
155	1 SET FRT GRILLE CLIPS	120.00	60
Labour			
156	1 TO CHECK WIRING	120.00	✓
157	1 TO REMOVE AND REFIT BOOTLID SPOILER	150.00	X
158	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	200.00	120
159	1 TO REMOVE AND REFIT REAR WINDSCREEN	150.00	X
160	1 TO REMOVE AND REFIT REAR VIEW CAMERA	80.00	50
161	1 TO REMOVE AND REFIT RH FENDER GLASS	120.00	60
162	1 TO REMOVE AND REFIT LH FENDER GLASS	120.00	60
163	1 TO REMOVE AND REFIT SEAT CUSHION & INNER TRIM	200.00	80
164	1 TO REMOVE AND REFIT REAR SEAT BELT	150.00	X
165	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
166	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
167	1 TO REMOVE AND REFIT FUEL TANK	150.00	60
168	1 TO SPRAY PANEL SEALANT	200.00	80
169	1 (REAR) TO SPRAY PAINTING	1500.00	1500
170	1 TO REMOVE AND REPLACE THE DAMAGED PARTS. KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1500.00	1800
171	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	120.00	X
172	1 TO CHECK WIRING	50.00	30
173	1 TO REFILL AIRCON GAS	120.00	60
174	1 TO SPRAY PANEL SEALANT	80.00	60
175	1 (FRONT) TO SPRAY PAINTING	1500.00	1800

Kang Car Repairers Pte Ltd

1 Kang Road, #02-01, Singapore 417883
TEL: 6747 7616 Fax: 6748 8677 Email: kangcar@singnet.com.sg
GST: 200002125

M/S: SMRT BUSES LTD
6 ANG MO KIO ST 62
SINGAPORE 569140

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4 V SR
Chassis No: ACR500078960
Reg. Date: 22.12.2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
176	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	SS 1,500.00	SS
		12,280.00	12,280.00
	Total		SS 60,641.38
	Add GST @ 7%		4,244.90
	Total Amount Payable		SS 64,886.28

TOTAL: SINGAPORE DOLLAR SIXTY FOUR THOUSAND EIGHT HUNDRED EIGHTY SIX AND CENTS TWENTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Lj
H/S 12/04/22
20 Days