

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chasis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID Distorted	1,490.90	✓
2	2 PCS BOOT LID HINGE Not New	130.60	✗
3	2 PCS BOOT LID SHOCK ABSORBER Damaged	493.60	✓
4	1 PC BOOT LID RUBBER Cut	325.70	✓
5	1 PC BOOT LID LOGO	66.80	✓
6	1 PC BOOTLID "ESTIMA" EMBLEM } New	74.20	✓
7	1 PC BOOTLID "AERAS" EMBLEM } New	51.60	✓
8	1 PC BOOT LID LAMP LH } Smashed	383.70	✓
9	1 PC BOOT LID LAMP RH } Smashed	383.70	✓
10	1 PC BOOTLID REFLECTOR LAMP Smashed	397.20	✓
11	1 PC BOOT LID CHROME Cracked	267.30	✓
12	2 PCS REAR NUMBER PLATE LAMP Cracked	131.80	✓
13	1 PC BOOTLID AUTO LOCK } Not New	899.70	✗
14	1 PC BOOTLID AUTO LOCK BUTTON } Not New	267.30	✗
15	1 PC BOOTLID LOCK Damaged	389.80	✓
16	1 PC BOOTLID LOCK COVER } Not New	35.30	✗
17	1 PC BOOT LID LOCK CHECKER } Not New	85.30	✗
18	2 PCS BOOT LID TOP CORNER RUBBER Not New	197.60	✗
19	1 PC BOOTLID RH SIDE STOPPER } Damaged	98.80	✓
20	1 PC BOOTLID LH SIDE STOPPER } Damaged	98.80	✓
21	1 PC BOOT LID TRIM Deformed	476.00	✓
22	2 PCS BOOTLID TRIM SIDE SMALL COVER Deformed	230.60	✓
23	1 PC BOOT LID OUTER OPENER HANDLE Not New	133.40	✗
24	1 PC REAR WIPER MOTOR Damaged	857.70	✓
25	1 PC REAR WIPER ARM Cut	202.70	✓
26	1 PC REAR WIPER BLADE New	61.60	✗
27	1 PC REAR WINDSCREEN GLASS Shattered	1,295.70	✓
28	2 PCS REAR WINDSCREEN INNER SIDE TRIM Cut	393.40	✓
29	1 PC REAR WINDSCREEN RUBBER New	125.70	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chassis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
30	1 PC REAR WINDSCREEN TOP TRIM <i>Not new</i>	233.70	X.
31	1 PC REAR BOOTLID SPOILER <i>Cracked</i>	1,702.10	✓
32	1 PC REAR BOOTLID HOLDER COVER <i>Missing</i>	41.40	✓
33	1 PC REAR FENDER RH <i>Buckled</i>	756.60	✓
34	1 PC REAR FENDER GLASS RH <i>Not new</i>	863.80	X.
35	1 PC REAR RH SLIDING DOOR RAIL <i>Not new</i>	466.50	X
36	1 PC REAR FENDER INNER TRIM RH <i>Deformed</i>	791.50	✓
37	1 PC REAR FENDER TOP TRIM RH <i>Cracked</i>	527.70	345
38	1 PC REAR FENDER COWLING RH <i>Not new</i>	285.20	X.
39	1 PC AIR CON BLOWER MOTOR <i>Cracked</i>	2,127.90	✓
40	1 UNIT REAR SEAT BELT RH <i>Not new</i>	723.70	X
41	1 PC REAR SEAT BELT COVER RH <i>Deformed</i>	178.70	✓
42	1 PC REAR SEAT BELT LH <i>Not new</i>	723.70	X
43	1 PC REAR SEAT BELT COVER LH <i>Deformed</i>	178.70	✓
44	1 PC REAR FENDER LH <i>Buckled</i>	756.30	✓
45	1 PC REAR FENDER GLASS LH <i>Shattered</i>	863.80	✓
46	1 PC REAR LH SLIDING DOOR RAIL <i>Not new</i>	466.50	X
47	1 PC REAR LH FENDER INNER TRIM <i>Deformed</i>	791.50	✓
48	1 PC REAR FENDER TOP TRIM LH <i>Cracked</i>	527.70	345
49	1 PC REAR SPARE TOOL BRACKET LH <i>Not new</i>	182.70	X
50	1 PC REAR SPARE TYRE JACK BRACKET LH <i>Not</i>	206.20	✓
51	1 PC REAR LH FENDER COWLING <i>Not new</i>	285.20	X
52	1 PC REAR LH FENDER JACK OUTER COVER <i>Deformed</i>	213.80	✓
53	1 PC TAIL LAMP - RH <i>Smashed.</i>	517.30	✓
54	1 PC TAIL LAMP PILLAR RH <i>Deformed.</i>	1,419.30	648
55	1 PC TAIL LAMP LH <i>Smashed.</i>	517.30	✓
56	1 PC TAIL LAMP PILLAR LH <i>Deformed.</i>	1,419.30	648
57	1 PC REAR PANEL <i>Distorted</i>	725.50	✓
58	1 PC REAR PANEL TRIM	260.50	✓
59	1 PC REAR PANEL BOTTOM TRIM <i>Deformed</i>	175.70	✓
60	1 PC REAR BOOT HARD COVER	1,090.10	865

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chasis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		SS	SS
61	1 PC SPARE TYRE PANEL <i>Repair</i>	782.80	X
62	1 PC SPARE TYRE TRIM <i>new</i>	323.30	X
63	1 PC REAR BUMPER <i>Deformed</i>	1,060.70	882
64	2 PCS REAR BUMPER SPONGE <i>crushed</i>	241.40	✓
65	2 PCS REAR BUMPER SCREW COVER <i>missing</i>	58.80	✓
66	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	136.80	✓
67	2 PCS REAR BUMPER SMALL RETAINER <i>new</i>	99.20	✓
68	2 PCS REAR BUMPER BRACKET <i>new</i>	143.20	X
69	2 PCS REAR TOWING COVER <i>Deformed</i>	79.20	✓
70	2 PCS REAR BUMPER REFLECTOR <i>crushed</i>	156.60	✓
71	1 PC REAR BUMPER MUDFLAP RH <i>new</i>	97.70	X
72	1 PC REAR CIGARETTE LIGHT SWITCH <i>damaged</i>	212.70	✓
73	1 PC REAR CIGARETTE LIGHT SWITCH COVER <i>Deformed</i>	48.40	✓
74	1 PC EXHAUST PIPE <i>new</i>	932.20	X
75	1 PC BONNET <i>Dented</i>	765.50	✓
76	2 PCS BONNET HINGE <i>Best</i>	164.40	✓
77	1 PC BONNET RUBBER <i>new</i>	59.90	X
78	1 PC BONNET LOCK <i>Damaged</i>	190.70	✓
79	1 PC BONNET LOCK CABLE <i>new</i>	52.90	X
80	1 PC FRT BRACE PANEL <i>new</i>	116.90	X
81	1 PC FRT BUMPER <i>Distorted</i>	1,216.70	965
82	1 PC FRT BUMPER SPONGE <i>crushed</i>	165.50	✓
83	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	483.10	381
84	1 PC FRT BUMPER TOP BEAM <i>Best</i>	361.20	182
85	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	172.00	✓
86	1 PC FRT BUMPER GRILLE <i>Deformed</i>	399.30	185
87	2 PCS FRT BUMPER BRACKET <i>new</i>	424.20	X
88	1 PC FRT FOG LAMP RH <i>crushed</i>	398.30	✓
89	1 PC FRT FOG LAMP LH <i>crushed</i>	398.30	✓
90	2 PCS FRT TOWING COVER <i>Deformed</i>	93.60	✓
91	1 PC HEADLAMP LH <i>crushed</i>	3,298.30	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chasis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
92	1 PC HEADLAMP RH <i>cracked</i>	3,298.30 ✓	
93	1 PC FRT SUPPORT PANEL <i>Buckled</i>	1,008.90 811	
94	1 PC FRT SUPPORT PANEL TOP TRIM <i>Deformed</i>	167.60 ✓	
95	1 PC FRT FENDER COWLING RH <i>3 torn</i>	268.10 ✓	
96	1 PC FRT FENDER COWLING LH <i>3 torn</i>	268.10 ✓	
97	1 PC FRT GRILLE <i>cracked</i>	707.60 587	
98	1 PC FRT GRILLE EMBLEM <i>Nec</i>	81.50 ✓	
99	1 PC FRT GRILLE RUBBER <i>ne new</i>	89.40 <i>x.</i>	
100	1 PC RADIATOR <i>Distorted.</i>	2,068.30 ✓	
101	2 PCS RADIATOR TOP BRACKET <i>Best.</i>	136.40 ✓	
102	2 PCS RADIATOR TOP BUZZ <i>new</i>	36.40 ✓	
103	2 PCS RADIATOR BOTTOM BUZZ <i>new</i>	33.60 ✓	
104	1 PC RADIATOR TOP GARNISH <i>cracked.</i>	198.70 ✓	
105	1 PC RADIATOR UNDER COVER <i>torn</i>	168.00 ✓	
106	1 PC RADIATOR FAN <i>ut.</i>	234.30 ✓	
107	1 PC RADIATOR FAN MOTOR <i>Damaged.</i>	643.70 ✓	
108	1 PC RADIATOR FAN COWLING <i>cracked.</i>	380.80 ✓	
109	1 PC AIRCON CONDENSER <i>Distorted.</i>	1,690.40 1345	
110	1 PC AIR CON FAN <i>ut.</i>	184.30 ✓	
111	1 PC AIRCON FAN MOTOR <i>Damaged.</i>	565.10 ✓	
112	1 PC AIRCON DISCHARGE PIPE <i>3 Best.</i>	662.10 325	
113	1 PC AIRCON RECEIVER PIPE <i>3 Best.</i>	272.10 ✓	
114	1 PC AIRCON LIQUID PIPE <i>3 Best.</i>	562.30 361	
115	1 PC AIRCON SUCTION HOSE <i>ne new</i>	754.20 <i>x.</i>	
116	2 PCS AIR CONDENSER BOTTOM BUZZ <i>new</i>	37.00 ✓	
117	2 PCS AIR CONDENSER SIDE GARNISH <i>Deformed</i>	57.60 ✓	
118	2 PCS AIR CONDENSER TOP BUZZ <i>new</i>	37.00 ✓	
119	2 PCS HORN <i>Damaged</i>	336.00 ✓	
120	1 PC FRONT WIPER WATER TANK <i>3 ne</i>	181.70 <i>x</i>	
121	1 PC FRONT WIPER WATER TANK MOTOR <i>3 ne</i>	243.20 <i>x.</i>	
122	1 PC AIR CLEANER OUTLET AIR DUCT <i>Deformed</i>	81.70 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chasis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
123	1 PC FRT ISOLATOR BOX <i>not me</i>	210.20 <i>x</i>	
124	1 PC FRT EXHAUST CATALYTIC CONVERTER <i>3 new</i>	1,881.21 <i>x</i>	
125	1 PC FRT EXHAUST CATALYTIC CONVERTER COVER <i>new</i>	268.70 <i>x</i>	
	<i>2 Pc Fog Lamp Cover 85 x 2 = 170.00</i>	61,014.71	
	Less 25%	15,253.68	45,761.38
	Special Net <i>ambd</i>		
126	1 SET BOOTLIDREFLECTOR LAMP CLIPS <i>new</i>	30.00 <i>✓</i>	
127	1 PC REAR NUMBER PLATE <i>Best</i>	50.00 <i>✓</i>	
128	1 SET BOOT LID TRIM CLIPS <i>new</i>	60.00 <i>30</i>	
129	1 PC REAR WINDSCREEN SEAL <i>3 new</i>	60.00 <i>30</i>	
130	1 PC REAR WINDSCREEN SEALANT <i>new</i>	60.00 <i>30</i>	
131	1 PC REVERSE CAMERA <i>Damaged</i>	480.00 <i>✓</i>	
132	1 PC REVERSE VIEW CAMERA <i>missing</i>	400.00 <i>350</i>	
133	1 SET REAR WINDSCREEN INNER SIDE TRIM CLIPS <i>new</i>	60.00 <i>30</i>	
134	1 SET REAR WINDSCREEN TOP TRIM CLIPS <i>new</i>	40.00 <i>x</i>	
135	1 PC REAR FENDER GLASS SEALANT RH <i>3 new</i>	60.00 <i>30</i>	
136	1 PC REAR FENDER GLASS SEAL RH <i>new</i>	60.00 <i>30</i>	
137	1 SET REAR FENDER INNER TRIM RH CLIPS <i>new</i>	60.00 <i>30</i>	
138	1 SET REAR FENDER TOP TRIM RH CLIPS <i>new</i>	60.00 <i>20</i>	
139	1 SET REAR FENDER COWLING CLIPS RH <i>not me</i>	60.00 <i>x</i>	
140	1 PC REAR FENDER GLASS SEAL LH <i>3 new</i>	60.00 <i>30</i>	
141	1 PC REAR FENDER GLASS LH SEALANT <i>new</i>	60.00 <i>30</i>	
142	1 SET REAR FENDER INNER TRIM CLIPS <i>new</i>	60.00 <i>30</i>	
143	1 SET REAR FENDER TOP TRIM CLIPS LH <i>new</i>	60.00 <i>20</i>	
144	1 SET REAR FENDER COWLING CLIPS LH <i>not me</i>	60.00 <i>x</i>	
145	1 SET REAR PANEL TRIM CLIPS <i>3 new</i>	40.00 <i>20</i>	
146	1 SET REAR BUMPER CLIPS	50.00 <i>30</i>	
147	1 SET REVERSE SENSORS <i>Damaged</i>	350.00 <i>200</i>	
148	1 SET REAR BUMPER MUDFLAP CLIPS RH <i>3 new</i>	30.00 <i>x</i>	
149	1 SET FRT BUMPER GRILLE CLIPS <i>new</i>	40.00 <i>x</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chasis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
150	1 PC FRT NUMBER PLATE <i>Best</i>	50.00	✓
151	1 SET FRT BUMPER CLIPS <i>Her</i>	40.00	30.
152	1 SET FRT SUPPORT PANEL TOP TRIM CLIPS <i>Her</i>	40.00	20.
153	1 SET FRT FENDER COWLING CLIPS RH <i>3M</i>	40.00	✓
154	1 SET FRT FENDER COWLING CLIPS LH <i>Her</i>	40.00	✓
155	1 SET FRT GRILLE CLIPS <i>Nec</i>	40.00	20.
		2.600.00	2.600.00
	Labour		
156	1 TO CHECK WIRING	50.00	30
157	1 TO REMOVE AND REFIT BOOTLID SPOILER	100.00	50.
158	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	✓
159	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
160	1 TO REMOVE AND REFIT REAR VIEW CAMERA	80.00	50
161	1 TO REMOVE AND REFIT RH FENDER GLASS	120.00	60.
162	1 TO REMOVE AND REFIT LH FENDER GLASS	120.00	60.
163	1 TO REMOVE AND REFIT SEAT CUSHION & INNER TRIM	380.00	120
164	1 TO REMOVE AND REFIT REAR SEAT BELT	150.00	✓
165	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
166	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
167	1 TO REMOVE AND REFIT FUEL TANK	150.00	60
168	1 TO SPRAY PANEL SEALANT	200.00	80
169	1 (REAR) TO SPRAY PAINTING	2,600.00	1800
170	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	4,600.00	2000.
171	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	120.00	✓
172	1 TO CHECK WIRING	50.00	30
173	1 TO REFILL AIRCON GAS	120.00	60
174	1 TO SPRAY PANEL SEALANT	80.00	60
175	1 (FRONT) TO SPRAY PAINTING	1,500.00	1200.

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : STRIDES AUTOMOTIVE SERVICES PTE LTD
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2022
TP Veh Reg No: SG1699R

Estimate No: EST2200103
Date: 09 Apr 2022
Veh Reg No: SKK808Z
Make/Model: TOYOTA ESTIMA
AERAS 2.4A SR
Chasis No: ACR500078960
Reg. Date: 22/12/2008
Your Ref No: SG1699R

Estimate Repair Cost to Vehicle No :SKK808Z

Quantity	Description	List Price	Amount
176	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	SS 1,500.00 12w.	SS
	7210	12,280.00	12,280.00
	Total	SS 60,641.38	
	Add GST @ 7%	4,244.90	
	Total Amount Payable	SS 64,886.28	

TOTAL: SINGAPORE DOLLAR SIXTY FOUR THOUSAND EIGHT HUNDRED EIGHTY SIX AND CENTS TWENTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
w/s 12/04/22
21 Days
total: 42260.85
4/s: 33.816