

ASS. REC. BY:

Taufikh

REF:

CS 3/AG/2100 6825/Tiv f3y3-1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMD 3157L

Policy No. _____


Claims No. C10010467/JM

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

\$3300

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

FRM5438X

Yr Regn: _____

2013, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Yamaha Jupiter MX

c.c

134

Colour _____

Black

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

MH350C002CK482675

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: (Nil) / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

80/90R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Aspira

Front

Rear

R/Bal. _____ mm

5

R/Bal. _____ mm

5

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 5/6/2021

D.O.I. 18/6/21 @ 6pm

Survey held at

Equator Butterwood

Des. of Damages (Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

buddy week

Repair Range: \$3000 - \$5000, 6 days

1/3/22 Taufikh informed LS \$3000 (red 4770, 61%)

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

2) 12/4/22-typist

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS SI


Photos

Others

TOTAL

Rep. Form: TP

Lump Sum / L.S. (\$ 3000)



EQUATOR BROTHERHOOD®

REGISTRATION NO: 53232274J

25 Kaki Bukit Road 4

Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391

Email: equator.brotherhood@gmail.com

PRE - REPAIR INSPECTION

Bike Model: Yamaha Jupiter MX135

Bike Plate: FBM5438X

S/N	Parts Description	Quantity	Unit Price	Amount
1	Yamaha fairing (colored)	1	\$ 400.00	\$ 400.00
2	Yamaha fairing (matte black)	1	\$ 180.00	\$ 180.00
3	Yamaha front suspension (left)	1	\$ 395.00	\$ 320 395.00
4	Yamaha front suspension (right)	1	\$ 395.00	\$ 320 395.00
5	Yamaha triple clamp (bottom)	1	\$ 250.00	\$ 185 250.00
6	Yamaha steering cone	1	\$ 95.00	\$ 95.00
7	Yamaha handlebar	1	\$ 95.00	\$ 95.00
8	Yamaha handlebar bracket	1	\$ 65.00	\$ 65.00
9	Yamaha headlight	1	\$ 220.00	\$ 220.00
10	Yamaha front signal (left)	1	\$ 45.00	\$ 45.00
11	Yamaha front signal (right)	1	\$ 45.00	\$ 45.00
12	Yamaha front rim	1	\$ 220.00	\$ 220.00
13	Yamaha front wheel bearings	2	\$ 35.00	\$ 40 70.00
14	Yamaha front wheel seal	2	\$ 15.00	\$ 30.00
15	Yamaha front wheel shaft	1	\$ 50.00	\$ 30 50.00
16	Yamaha front brake disc	1	\$ 130.00	\$ 130.00
17	Yamaha front brake caliper	1	\$ 220.00	\$ 220.00
18	Yamaha brake lever	1	\$ 45.00	\$ 45.00
19	Yamaha front brake master cylinder	1	\$ 150.00	\$ 150.00
20	Yamaha front brake master cylinder bracket	1	\$ 25.00	\$ 25.00
21	Yamaha front brake hose	1	\$ 95.00	\$ 95.00
22	Yamaha front tire valve	1	\$ 15.00	\$ 15.00
23	Yamaha clutch lever	1	\$ 45.00	\$ 45.00
24	Yamaha clutch cable	1	\$ 45.00	\$ 45.00
25	Yamaha clutch cable length adjuster	1	\$ 20.00	\$ 20.00

Equator Brotherhood®

REGISTRATION NO: 53232274J

REGISTRATION NO:53232274J

25 Kaki Bukit Road 4
Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391
Email: equator.brotherhood@gmail.com


PRE - REPAIR INSPECTION

Bike Model: Yamaha Jupiter MX135

Bike Plate: FBM5438X

S/N	Parts Description	Quantity	Unit Price	Amount
26	Yamaha clutch lever holder	1	\$ 45.00	\$ 45.00
27	Yamaha clutch lever holder screw	1	\$ 10.00	\$ 10.00
28	Yamaha exhaust	1	\$ 420.00	\$ 420.00
29	Yamaha exhaust cover (black)	1	\$ 45.00	\$ 45.00
30	Yamaha exhaust cover (silver)	1	\$ 65.00	\$ 65.00
31	Yamaha exhaust gasket	1	\$ 15.00	\$ 15.00
32	Yamaha mirror set	2	\$ 35.00	\$ 70.00
33	Yamaha foot step bar	1	\$ 65.00	\$ 65.00
34	Yamaha rider footrest	2	\$ 25.00	\$ 50.00
35	Yamaha pillion foot rest bracket	2	\$ 65.00	\$ LHX 130.00
36	Yamaha pillion foot rest	2	\$ 25.00	\$ LHX ^m 50.00
37	Yamaha brake pedal	1	\$ 45.00	\$ 45.00
38	Yamaha throttle tube	1	\$ 25.00	\$ 25.00
39	Yamaha throttle cable	1	\$ 45.00	\$ 45.00
40	Yamaha rear brake master cylinder	1	\$ 160.00	\$ 160.00
41	Yamaha front opened basket	1	\$ 60.00	\$ 60.00
42	Yamaha meter	1	\$ 280.00	\$ 280.00
43	Yamaha meter cable	1	\$ 65.00	\$ 65.00
44	Yamaha gear shifter	1	\$ 45.00	\$ 45.00
45	Yamaha gear shifter rubber	1	\$ 10.00	\$ 10.00
46	Yamaha side stand	1	\$ 45.00	\$ 45.00
47	Yamaha side stand spring	1	\$ 15.00	\$ 15.00
48	Yamaha side main stand	1	\$ 60.00	\$ 60.00
49	Yamaha main stand spring	1	\$ 15.00	\$ 15.00
50	Yamaha radiator set	1	\$ 280.00	\$ 280.00
51	Yamaha radiator fan + motor	1	\$ 85.00	\$ 85.00

X un
X un
bt —
cut —
cut —
the ✓
out ✓
bt ✓
di's ✓
bro ✓ RH
RH mis ✓
dd —
X un
X un
cut —
de —
X }
X }
X }
X }
X } un
X }
X }
X }
bt —
X un



EQUATOR BROTHERHOOD®

REGISTRATION NO: 53232274J

25 Kaki Bukit Road 4

Synergy@KB #03-79 Singapore (417800)

Contact: 63846939 / 90113391

Email: equator.brotherhood@gmail.com

PRE - REPAIR INSPECTION

Bike Model: Yamaha Jupiter MX135

Bike Plate: FBM5438X

S/N	Parts Description	Quantity	Unit Price	Amount
52	Yamaha engine cover	1	\$ 180.00	\$ 180.00
53	Yamaha engine cover gasket	1	\$ 20.00	\$ 20.00
54	Motul engine oil	1	\$ 30.00	\$ 30.00
55	Motul coolant	1	\$ 50.00	\$ 50.00
56	Motul brake fluid	1	\$ 20.00	\$ 20.00
57	Grip set	1	\$ 45.00	\$ 45.00
58	CNC bar end balancer	1	\$ 120.00	\$ 120.00
59	IU	1	\$ 175.00	\$ 175.00
60	IU bracket	1	\$ 25.00	\$ 25.00
61	Kappa box rack	1	\$ 110.00	\$ 110.00
62	Kappa box 39L	1	\$ 210.00	\$ 210.00
63	Kappa box base plate	1	\$ 85.00	\$ 85.00
64	Towing 1-trip (Workshop to reporting center)	1	\$ 65.00	\$ 65.00
65	Towing 1-trip (Reporting center to workshop)	1	\$ 65.00	\$ 65.00
66	Towing 1-trip (TP compound to workshop)	1	\$ 65.00	\$ 65.00
67	Chassis alignment	1	\$ 480.00	\$ 480.00
68	Labor	1	\$ 480.00	\$ 480.00
69			\$ -	\$ -
70	LKK Auto Consultants hence notify the Repairer of the following:		\$ -	\$ -
71	• To resurvey before/after spray painting		\$ -	\$ -
72	• To display damaged part(s) during resurvey		\$ -	\$ -
73	• Parts prices are subject to confirmation		\$ -	\$ -
74	• Third party survey is on a "Without Prejudice" basis		\$ -	\$ -
75	• No illegal modification(s) is allowed		\$ -	\$ -
76	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		\$ -	\$ -
	Acknowledged by Repairer		\$ -	\$ -
	Signature:			
	Date:			
		Total:	\$	7,770.00

X }
X }
X }
X }
new ✓
cut ✓
cut ✓
X un
X un
cut ✓
mis ✓
cut ✓
400
400
X un
X un
200

3915
10% 3523.50
280
3803.50
4593000
5 days

Equator Brotherhood®
REGISTRATION NO: 53232274J