

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 08 Dec 2022

Preliminary Advice

Insured Vehicle No	: YQ3082H	Accident Date	: 11/04/2022
TP Vehicle No	: GZ5837A	Assignment Date	: 12/04/2022
Make	: TOYOTA DYNA 1.5T	Est. Duration of Repair	: 10
Date of Inspection	: 13/04/2022		
Inspection At	: UNIMOTOR CO (HQ) NO 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,079.72
Revised Amount	:S\$	14,792.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,792.60
Lump Sum Repair	:S\$	11,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :