



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003386/Kty3n2	
			Date: 19/05/2022	
			Code: AIS	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBJ 1510L	Veh. Inspected	SLL 2512X
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004493SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	12/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	BMW X4 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WBAUJ32060LK54868	Colour	METALLIC DARK BLUE
	Odometer	44951 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/45 R20	MICHELIN	9 mm
	L/H Front Tyre	245/45 R20	MICHELIN	9 mm
	R/H Rear Tyre	245/45 R20	MICHELIN	9 mm
	L/H Rear Tyre	245/45 R20	MICHELIN	9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	08/04/2022	Inspection Date	18/04/2022
	Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	