

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9748 9940 Fax: 6346 7213

Vehicle No.: SMC 6656Z

Model: BMW 535i

not Authorized
LKK
1/5 \$ 4550
12/4/22
3 days.

QTY	List Price:
1	Rear boot lid
1	Rear boot logo
1	Rear bumper PDC sensor @ 369.00
1	Rear bumper undercover
1	Rear bumper reinforcement
1	Rear end panel
1	Rear bumper top retain
1	Rear bumper inner frame garnish
1	Rear bumper side holders @ 139.30
2	Rear taillamps @ 841.20

225 x 2 = 450

261.23

681.00

Less 5%

Prices \$
R 1658.00 X
11 79.00 X
shut 1436.00 2/15
cre 176.50
11 685.00
R 923.40 X
cre 340.00
cre 289.00
N/S cre 278.00 1 PC
N/S cre 1682.40 1 PC
7547.30
-377.37

Subtotal 7169.94 7208.51

QTY	List Price
1 Set	Rear bumper clip
1	Rear M sport bumper
1	Rear M sport bumper lower lid
1	Rear bumper towing cover
2	Rear bumper reflector @ 130.00

11 60.00
11 2300.00 1600
11 680.00 300
11 42.00 X
11 260.00 X

Subtotal 3342.00

Labour Charges:

Panel beating.
To re-spray painting on the affected areas.
To apply undercoating
To remove and refit rear reverse sensor
To remove, replace damaged lamp and check rear wiring

1000.00	500
1000.00	600
11 100.00 X	
11 100.00	50
100.00	30
Subtotal	2300.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 12811.94 12850.51

2-268203
58

2547.92

5N-1960

L-1180

5687.92

202

4510

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: