

ASS. REC. BY:

REF:

CS/CT 22003398/Any3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBLS231E Yr Regn: 2021/Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BYD T3 C.C. —

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 14600 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LC0CE4PB6M0020766

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16C

R: 195/60R16C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kinglong

Front — Rear —

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. — D.O.I. 13/04/22

Survey held at Kai Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Check</u>
	<u>14/7/22 Lump Sum \$3400 and 5 days</u>
	<u>(Red. \$3674.49, 52%)</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?

1) 14/7/22

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

Survey Fee:

Transportation:

— S + RS — SI

Photos

Others

Report Format: TP - menmen

Lump Sum / R.P. / 3400



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 12/04/2022

Attn: The Motor Claims Department
Your Insured veh no: SLD 2628 M

WITHOUT PREJUDICE
(By Email Only)

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 AXA Tower
Spring Leaf Tower
Singapore 079909
Tel: 6388 6111

Cecilia 63896530

Huiyong

Dear Sir / Madam

Estimated Cost of repair for vehicle BYD-T3 GBL 5231 E And SLD 2628 M ON 02/04/2022 AT 22:38PM.

To Supply:

1pc	Rear Fender RH	Bucleed		\$ 1,892.00	✓
1pc	Rear Lamp RH	2pc new		\$ 563.50	✓
1pc	Rear Air Garnish	Canceled		\$ 146.35	✓
1pc	Rear Bumper	Replaced		\$ 874.30	✓
2pcs	Rear Bumper Bracket	2pc new	2pcs X \$59.80	\$ 119.60	39.80
2pcs	Rear Bumper Side Retainer	2pc new	2pcs X \$58.50	\$ 117.00	58.50
1pc	Retaining Plate Assy	2pc new		\$ 558.90	✓
1pc	Rear Door Lock Assy	new		\$ 373.00	✓
1pc	Vent Sidewall Plate RH	2pc new		\$ 49.00	✓
1pc	Trim Panel Assy, Guide Rail RH	new		\$ 177.40	✓
				\$ 4,871.65	
			Less 10%	\$ 487.17	
				\$ 4,384.49	
1pc	Reverse Sensor	Damaged	250	\$ 400.00	S/Nett 250
				\$ 4,784.49	

To dismantle & replace damage parts, panel beat where necessary

To putty & spray primer & spray paint on the affected portion.

To remove old paint & hence notify the Repairer of the following:

To check & ring functions after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 950.00 600

\$ 1,100.00 600 1290

\$ 420.00 60

\$ 120.00 30

\$ 7,074.49

total: 4267.85

4/5: 3.4K

Adrian
c/s 13/04/22

05 days