

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22003399/APA3Q2**Date:** 23/12/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SKU9706Y **Insured Vehicle No :** SLS4150G
 Date of Loss: 09/04/2022 Nature of Claim: TP Claim No: MFL2022D0001838

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU9706Y**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZR524775
 Reg. Date: 25/08/2015 (Man. Year: 2015) Chassis No: MR053REH104536892
 Colour: White Odometer: 256982 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,243.42	7,884.38	11,359.04	59.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	2,380.00	2,800.00	54.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,423.42	10,264.38	14,159.04	57.97
Approved Total (Overridden) (S\$)		8,100.00		
Nett Amount (S\$)	24,423.42	8,100.00	16,323.42	66.84
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/04/2022
 Date Inspected: 13/04/2022 Inspected At: T & C Automotive (HQ)
 1 KAKI BUKIT AVE 6,, #01-49, AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU9706Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	483.23 FL	*483.23 FL
2	1		*REAR BUMPER SIDE RETAINER RH (LONG)	Necessary	105.21 FL	*105.21 FL
3	1		*REAR BUMPER SIDE RETAINER RH (SHORT)	Not Necessary	67.24 FL	*- FL
4	1		*REAR BUMPER CORNER RETAINER RH (L)	Not Necessary	65.70 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER LH (LONG)	Not Necessary	105.21 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER LH (SHORT)	Not Necessary	67.24 FL	*- FL
7	1		*REAR BUMPER CORNER RETAINER LH (L)	Not Necessary	65.70 FL	*- FL
8	1		*REAR BUMPER RH REFLECTOR	Not Necessary	56.50 FL	*- FL
9	1		*REAR BUMPER LH REFLECTOR	Not Necessary	56.50 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	379.30 FL	*379.30 FL
11	1		*REAR BUMPER FOAM	Not Necessary	123.00 FL	*- FL
12	1		*BOOT LID	Repair	655.50 FL	*- FL
13	1		*BOOT LID TRIMBOARD	Not Necessary	172.30 FL	*- FL
14	1		*BOOT LID CABLE	Not Necessary	67.60 FL	*- FL
15	2		*BOOT LID HINGES	Not Necessary	175.00 FL	*- FL
16	1		*BOOT LID LOCK	Not Necessary	379.20 FL	*- FL
17	1		*BOOT LID LOWER CATCH	Not Necessary	46.70 FL	*- FL
18	1		*BOOT LID COROLLA EMBLEM	Necessary	45.20 FL	*45.20 FL
19	1		*BOOT LID ALTIS EMBLEM	Necessary	43.20 FL	*43.20 FL
20	1		*BOOT LID TOYOTA LOGO	Necessary	39.80 FL	*39.80 FL
21	1		*BOOT LID CHROME	Not Necessary	231.30 FL	*- FL
22	1		*BOOT LID REFLECTOR RH	Not Necessary	326.30 FL	*- FL
23	1		*BOOT LID REFLECTOR LH	Not Necessary	326.30 FL	*- FL
24	1		*TAIL LAMP RH	Not Necessary	368.70 FL	*- FL
25	1		*TAIL LAMP LH	Not Necessary	368.70 FL	*- FL
26	1		*REAR END PANEL	Dented	552.50 FL	*552.50 FL
27	1		*REAR END PANEL GARNISH	Deformed	229.60 FL	*229.60 FL
28	1		*EXHAUST SILENCER	Not Necessary	920.80 FL	*- FL
29	1		*EXHAUST HEATSHIELD	Not Necessary	37.00 FL	*- FL
30	1		*SPARE TYRE BOARD	Not Necessary	348.10 FL	*- FL
31	1		*SPARE TYRE CARRIER	Not Necessary	74.10 FL	*- FL
32	1		*SPARE TYRE PANEL	Not Necessary	757.00 FL	*- FL
33	1		*FRONT BONNET	Repair	840.00 FL	*- FL
34	1		*FRONT BONNET STAND	Not Necessary	85.00 FL	*- FL
35	1		*FRONT BONNET STAND CLIP	Not Necessary	5.00 FL	*- FL
36	1		*FRONT BONNET LOCK	Not Necessary	98.00 FL	*- FL
37	1		*FRONT BONNET LOCK CABLE	Not Necessary	58.00 FL	*- FL
38	2		*FRONT BONNET HINGE	Not Necessary	120.00 FL	*- FL
39	1		*FRONT BONNET INSULATOR	Not Necessary	285.00 FL	*- FL
40	1		*FRONT GRILLE	Cracked	486.00 FL	*486.00 FL
41	1		*FRONT GRILLE TOYOTA LOGO	Necessary	68.00 FL	*68.00 FL
42	1		*FRONT BUMPER	Deformed	555.80 FL	*555.80 FL
43	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	125.00 FL	*- FL
44	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	345.00 FL	*- FL
45	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	58.00 FL	*- FL
46	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	58.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FOG LAMP RH	Not Necessary	279.55 FL	*- FL
48	1		*FOG LAMP LH	Not Necessary	279.55 FL	*- FL
49	1		*FOG LAMP GARNISH RH	Not Necessary	158.00 FL	*- FL
50	1		*FOG LAMP GARNISH LH	Not Necessary	158.00 FL	*- FL
51	1		*HEADLAMP RH	Creased	2,735.00 FL	*2,735.00 FL
52	1		*HEADLAMP LH	Cracked	2,735.00 FL	*2,735.00 FL
53	1		*HEADLAMP CHROME RH	Not Necessary	225.00 FL	*- FL
54	1		*HEADLAMP CHROME LH	Not Necessary	225.00 FL	*- FL
55	1		*FRONT SUPPORT PANEL	Repair	705.00 FL	*- FL
56	1		*FRONT BRACE PANEL	Bent	113.00 FL	*113.00 FL
57	1		*HORN	Not Necessary	98.70 FL	*- FL
58	1		*RADIATOR	Not Necessary	1,968.00 FL	*- FL
59	1		*RADIATOR FAN BLADE	Not Necessary	175.00 FL	*- FL
60	1		*RADIATOR FAN MOTOR	Not Necessary	471.10 FL	*- FL
61	1		*RADIATOR FAN COWLING	Not Necessary	240.00 FL	*- FL
62	1		*AIR-CON CONDENSER	Dented	1,475.00 FL	*1,475.00 FL
63	1		*AIR-CON DISCHARGE PIPE	Not Necessary	395.80 FL	*- FL
64	1		*AIR-CON SUCTION PIPE	Not Necessary	375.80 FL	*- FL
65	1		*AIR-CON LIQUID PIPE	Not Necessary	695.00 FL	*- FL
66	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
67	1		*REAR NUMBER PLATE W/CASING	Not Necessary	180.00 FS	*- FS
68	10		*REAR BUMPER CLIP	Necessary	43.00 FS	*30.00 FS
69	10		*REAR END PANEL GARNISH CLIP	Necessary	43.00 FS	*10.00 FS
70	1		*COOLANT	Not Necessary	80.00 FS	*- FS
71	8		*BOOT LID TRIMBOARD CLIP	Not Necessary	34.40 FS	*- FS
72	1		*FRONT NUMBER PLATE W/CASING	Cut	180.00 FS	*60.00 FS
73	10		*FRONT BUMPER CLIP	Necessary	43.00 FS	*30.00 FS
74	8		*FRONT BONNET INSULATOR CLIP	Not Necessary	34.40 FS	*- FS
75	1		*FRONT GRILLE CLIP	Necessary	30.10 FS	*20.00 FS
			(7 PCS)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,351.93	10,395.84
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,108.51	2,511.46
Total Parts (\$\$)	19,243.42	7,884.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRONT -PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	400.00
2	REAR -PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,200.00	600.00
3	FRONT -PUTTY AND SPRAY PAINTING AFFECTED AREAS	New	1,000.00	400.00
4	REAR -PUTTY AND SPRAY PAINTING AFFECTED AREAS	New	1,200.00	800.00
5	REWIRING	New	120.00	60.00
6	TO SPRAY ANTI-RUST UNDERCOAT	New	150.00	60.00
7	TO REMOVE AND REPLACE EXHAUST SILENCER	New	150.00	0.00
8	TO REMOVE AND REPLACE DAMAGED AIR-CON CONDENSER AND TO VACUUM AIR-CON SYSTEM AND CHARGE UP AIR-CON GAS	New	280.00	60.00
9	TO REMOVE AND REPLACE RADIATOR AND ELECTRIC FANS AND TO CONDUCT PRESSURE TEST	New	280.00	0.00
Gross Labour Cost (S\$)			5,180.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >