

ESTIMATE

T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49 AUTOBAY@KAKI BUKIT, SINGAPORE 417883
CONTACT : 9007 5148, AH CHAI

Date : 12/04/2022

Vehicle Number : SKU9706Y
Chassis Number : MR053REH104536892
Make/Model : Toyota Corolla Altis

T P Grab.
Xiao Tony

Descriptions	Qty	Unit Price	Amount
Spare Parts			
Rear bumper <i>Red</i>	1	\$483.23	✓ \$483.23
Rear bumper side retainer RH (long) <i>new</i>	1	\$105.21	✓ \$105.21
Rear bumper sider retainer RH (short) <i>new</i>	1	\$67.24	+ \$67.24
Rear bumper corner retainer RH (L) <i>new</i>	1	\$65.70	+ \$65.70
Rear bumper side retainer LH (long) <i>new</i>	1	\$105.21	+ \$105.21
Rear bumper sider retainer LH (short) <i>new</i>	1	\$67.24	+ \$67.24
Rear bumper corner retainer LH (L)	1	\$65.70	+ \$65.70
Rear bumper RH reflector <i>new</i>	1	\$56.50	+ \$56.50
Rear bumper LH reflector <i>new</i>	1	\$56.50	+ \$56.50
Rear bumper reinforcement <i>Red</i>	1	\$379.30	✓ \$379.30
Rear bumper foam <i>new</i>	1	\$123.00	x \$123.00
Bood lid <i>Repair</i>	1	\$655.50	+ \$655.50
Boot lid trimboard <i>new</i>	1	\$172.30	+ \$172.30
Boot lid cable <i>new</i>	1	\$67.60	+ \$67.60
Boot lid hinges <i>new</i>	2	\$87.50	+ \$175.00
Boot lid lock <i>new</i>	1	\$379.20	+ \$379.20
Bood lid lower catch <i>new</i>	1	\$46.70	+ \$46.70
Boot lid "Corolla" emblem <i>new</i>	1	\$45.20	✓ \$45.20
Boot lid "Altis" emblem <i>new</i>	1	\$43.20	✓ \$43.20
Boot lid "Toyota" logo <i>new</i>	1	\$39.80	✓ \$39.80
Boot lid chrome <i>new</i>	1	\$231.30	+ \$231.30
Boot lid reflector RH <i>new</i>	1	\$326.30	+ \$326.30
Boot lid reflector LH <i>new</i>	1	\$326.30	+ \$326.30
Tail lamp RH <i>new</i>	1	\$368.70	+ \$368.70
Tail lamp LH <i>new</i>	1	\$368.70	+ \$368.70
Rear end panel <i>Red</i>	1	\$552.50	✓ \$552.50
Rear end panel garnish <i>Red</i>	1	\$229.60	✓ \$229.60
Exhaust silencer <i>new</i>	1	\$920.80	+ \$920.80
Exhaust heatshield <i>new</i>	1	\$37.00	+ \$37.00
Spare tyre board <i>new</i>	1	\$348.10	+ \$348.10
Spare tyre carrier <i>new</i>	1	\$74.10	+ \$74.10
Spare tyre panel <i>new</i>	1	\$757.00	+ \$757.00
Front bonnet <i>Repair</i>	1	\$840.00	+ \$840.00
Front bonnet stand <i>new</i>	1	\$85.00	x \$85.00
Front bonnet stand clip <i>new</i>	1	\$5.00	+ \$5.00
Front bonnet lock <i>new</i>	1	\$98.00	+ \$98.00
Front bonnet lock cable <i>new</i>	1	\$58.00	+ \$58.00
Front bonnet hinge <i>new</i>	2	\$60.00	+ \$120.00
Front bonnet insulator <i>new</i>	1	\$285.00	+ \$285.00
Front grille <i>new</i>	1	\$486.00	✓ \$486.00
Front grille "Toyota" logo <i>new</i>	1	\$68.00	✓ \$68.00
Front bumper <i>Red</i>	1	\$555.80	✓ \$555.80
Front bumper lower grille <i>new</i>	1	\$125.00	x \$125.00
Front bumper reinforcement <i>new</i>	1	\$345.00	x \$345.00

ESTIMATE

T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49 AUTOBAY@KAKI BUKIT, SINGAPORE 417883
CONTACT : 9007 5148, AH CHAI

Date : 12/04/2022

Vehicle Number : SKU9706Y
Chassis Number : MR053REH104536892
Make/Model : Toyota Corolla Altis

Descriptions	Qty	Unit Price	Amount
Front bumper side retainer RH <i>new</i>	1	\$58.00	+ \$58.00
Front bumper side retainer LH <i>new</i>	1	\$58.00	+ \$58.00
Fog lamp RH	1	\$279.55	+ \$279.55
Fog lamp LH	1	\$279.55	+ \$279.55
Fog lamp garnish RH <i>new</i>	1	\$158.00	+ \$158.00
Fog lamp garnish LH <i>new</i>	1	\$158.00	+ \$158.00
Headlamp RH <i>could</i>	1	\$835.00	- 2735
Headlamp LH <i>could</i>	1	\$835.00	- 2735
Headlamp chrome RH <i>new</i>	1	\$225.00	+ \$225.00
Headlamp chrome LH <i>new</i>	1	\$225.00	+ \$225.00
Front support panel <i>new</i>	1	\$705.00	+ \$705.00
Front brace panel <i>Best</i>	1	\$113.00	+ \$113.00
Horn <i>new</i>	1	\$98.70	+ \$98.70
Radiator <i>new</i>	1	\$1,968.00	+ \$1,968.00
Radiator fan blade <i>new</i>	1	\$175.00	+ \$175.00
Radiator fan motor <i>new</i>	1	\$471.10	+ \$471.10
Radiator fan cowling <i>new</i>	1	\$240.00	+ \$240.00
Air-con condenser <i>Dented</i>	1	\$1,475.00	+ \$1,475.00
Air-con discharge pipe <i>new</i>	1	\$395.80	+ \$395.80
Air-con suction pipe <i>new</i>	1	\$375.80	+ \$375.80
Air-con liquid pipe <i>new</i>	1	\$695.00	+ \$695.00
			\$7,739.73
		Less 25%	\$1,934.93
		Sub Total 1	\$5,804.80
Spare Parts (S/Nett)			
Reverse sensor (set) <i>Dand</i>	1	\$250.00	20 \$250.00
Rear number plate w/casing <i>new</i>	1	\$180.00	+ \$180.00
Rear bumper clip <i>new</i>	10	\$4.30	30 \$43.00
Rear end panel garnish clip <i>new</i>	10	\$4.30	10 \$43.00
Coolant <i>new</i>	1	\$80.00	+ \$80.00
Boot lid trimboard clip <i>new</i>	8	\$4.30	+ \$34.40
Front number plate w/casing <i>cut</i>	1	\$180.00	60 \$180.00
Front bumper clip <i>new</i>	10	\$4.30	30 \$43.00
Front bonnet insulator clip <i>new</i>	8	\$4.30	+ \$34.40
Front grille clip <i>new</i>	7	\$4.30	20 \$30.10
		Sub-Total 2	\$917.90

Labour

Front - Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.

Front - Putty and spray painting affected areas.

Rear - Putty and spray painting affected areas.

Rewiring

To spray anti-rust undercoat.

4w \$800.00
60w \$1,200.00
4w \$1,000.00
8w \$1,200.00
60 \$120.00
60 \$150.00

ESTIMATE T & C AUTOMOTIVE

1 KAKI BUKIT AVENUE 6, #01-49 AUTOBAY@KAKI BUKIT, SINGAPORE 417883
CONTACT : 9007 5148, AH CHAI

Date : 12/04/2022

Vehicle Number : SKU9706Y

Chassis Number : MR053REH104536892

Make/Model : Toyota Corolla Altis

Descriptions	Qty	Unit Price	Amount
To remove and replace exhaust silencer.			X \$150.00
To remove and replace damaged air-con condenser and to vacuum air-con system and charge up air-con gas.			60 \$280.00
To remove and replace radiator and electric fans and to conduct pressure test.			X \$280.00
Total Labour			\$4,620.00
2380 Total Repair Cost			\$4,858.70

Adrian L
w/s 13/04/22
09 Days

total: 10179.63

L/s: 8.1K

8.1K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: