



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203161

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 26/05/2022
Reference CC6/CTI22003401/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKJ 1241G
Insured Veh. GBL 837R
Claim No. SNM22D202440C02
Policy No. DMCVSNA00032902201
Accident Date 08/04/2022
Inspection Date 12/04/2022

Description	Total
Survey Inspection	280.00
Digital Photographs	
Transportation	
Subtotal	280.00
GST (7%)	19.60
Grand Total	299.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22003401/Aea3q2 Date: 26/05/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBL 837R	Veh. Inspected	SKJ 1241G	
Policy No.	DMCVSNA00032902201	Coverage (\$)	0.00	
Claim No.	SNM22D202440C02	Excess (\$)	0.00	
Assign From		Assign Date	12/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTDGJ20W405003210	Colour	SILVER	
Odometer	240163 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	MICHELIN	6 mm	
L/H Front Tyre	215/50 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/50 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/50 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2022	Inspection Date	12/04/2022	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 1241G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	DENTED	1,250.00	1,250.00
1	FRONT DOOR PROTECTOR RH	DEFORMED	145.00	145.00
1	FRONT DOOR PROTECTOR CHROME RH	DEFORMED	35.00	35.00
1	FRONT DOOR WEATHERSTRIP RH	NOT NECESSARY	341.00	-
1	FRONT DOOR SASH PILLAR BLACK STICKER RH	NECESSARY	85.00	85.00
1	FRONT DOOR OUTER MOULDING RH	NOT NECESSARY	295.00	-
1	REAR DOOR RH	DENTED	1,285.00	1,285.00
1	REAR DOOR PROTECTOR RH	DEFORMED	155.00	155.00
1	REAR DOOR PROTECTOR CHROME RH	DEFORMED	40.00	40.00
2	REAR DOOR HINGES	NOT NECESSARY	160.00	-
1	REAR DOOR STRIKER RH	NOT NECESSARY	75.00	-
1	REAR DOOR POWER WINDOW REGULATOR RH	NOT NECESSARY	268.00	-
1	REAR DOOR P/W REGULATOR MOTOR RH	NOT NECESSARY	350.00	-
2	REAR DOOR BLACK SASH PILLAR STICKER RH	NECESSARY	85.00	85.00
1	REAR DOOR OUTER MOULDING RH	NOT NECESSARY	298.00	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	352.00	-
1	REAR DOOR TRIMBOARD RH	NOT NECESSARY	545.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,113.00	-
1	REAR WHEEL HUB W/BEARING RH	NOT NECESSARY	379.00	-
1	SIDE SKIRT RH	NOT NECESSARY	685.00	-
	LESS 25% DISCOUNT		-1,985.25	-770.00
			5,955.75	2,310.00
	<u>SPECIAL NETT ITEMS</u>			
8	REAR DOOR TRIMBOARD CLIPS @\$5.00 (SN)	NOT NECESSARY	40.00	-
1	REAR SPORTS RIM RH (SN)	CUT	450.00	400.00
			490.00	400.00
	<u>LABOUR</u>			
	TO CHECK WIRING .		60.00	30.00

Report Ref No. CC6/CTI22003401/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		800.00	400.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS .		1,000.00	600.00
	ANTI-RUST UNDERCOATING.		60.00	40.00
	TO CHECK AND ALIGN WHEELS WITH COMPUTERIZED WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE AND REPLACE REAR WHEEL HUB W/BEARING RH .	NOT NECESSARY	120.00	-
			2,160.00	1,150.00
GRAND TOTAL			8,605.75	3,860.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00
---	--	--	--	-----------------

Report Ref No. CC6/CTI22003401/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKJ 1241G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

