

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Date : 11/04/2022

Asher.

TO: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Our Customer : Eka Chan Lye Hsuan

Vehicle No : SKJ1241G

Model : Toyota Wish 2.0 Auto

Manufacture Year : 2010 (COE: 29/7/2030)

Date of Accident : 08/04/2022

Total Estimate Repair Days : 7

Total Pages : 2

Attn : Motor Claims Department

Fax : 6224 7478/7175

JTDGJ20W405203210

Re: Repair Estimate For Third Party Claim against GBL837R

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front door RH <i>Revised</i>	1		1250 \$0.00	✓
2	Front door protector RH <i>Revised</i>	1		145 \$0.00	✓
3	Front door protector chrome RH <i>Revised</i>	1		35 \$0.00	✓
4	Front door weatherstrip RH <i>new</i>	1		341 \$0.00	+
5	Front door sash pillar black sticker RH <i>new</i>	1		85 \$0.00	✓
6	Front door outer moulding RH <i>new</i>	1		295 \$0.00	+
7	Rear door RH <i>Revised</i>	1		1285 \$0.00	✓
8	Rear door protector RH <i>Revised</i>	1		155 \$0.00	✓
9	Rear door protector chrome RH <i>Revised</i>	1		40 \$0.00	✓
10	Rear door hinges <i>new</i>	2		160 \$0.00	+
11	Rear door striker RH <i>new</i>	1		75 \$0.00	+
12	Rear door power window regulator RH <i>new</i>	1		268 \$0.00	+
13	Rear door p/w regulator motor RH <i>new</i>	1		350 \$0.00	+
14	Rear door black sash pillar sticker RH <i>new</i>	2		85 \$0.00	✓
15	Rear door outer moulding RH <i>new</i>	1		298 \$0.00	+
16	Rear door weatherstrip RH <i>new</i>	1		352 \$0.00	+
17	Rear door trimboard RH <i>new</i>	1		545 \$0.00	+
18	Rear fender RH <i>Repair</i>	1	repair	1113 repair	+
19	Rear wheel hub w/bearing RH <i>new</i>	1		379 \$0.00	+
20	Side skirt RH <i>new</i>	1	repair	685 repair	+
				3080	
				2310	
			Sub-Total	\$0.00	
			Less 25%	\$0.00	
			Sub-Total 1	\$0.00	
B.	Spare Parts (S/Nett)				
1	Rear door trimboard clip <i>new</i>	8	\$5.00	\$40.00	+
2	Rear sports rim RH <i>new cut</i>	1	\$450.00	\$450.00	400
			Sub-Total 2	\$490.00	
			Total for Parts	\$490.00	

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
C.	Labour				
1	To check wiring.			\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	400
3	Spray painting all affected parts & areas.			\$1,000.00	600
4	Anti-rust undercoating.			\$60.00	40
5	To check and align wheels with computerized wheel alignment.			\$120.00	80
6	To remove and replace rear wheel hub w/bearing RH.			\$120.00	80
	Total Labour			\$1,920.00	
	Total Repair Cost			\$2,410.00	

1150

Adnan
h/s 12/04/22
04 Days

total: 3860

h/s: 3050.

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: