Our Date	Job Re	ef No :	305511922 21.04.2022		COMFORTDELGRO			
FIN	ALIZAT	ION FORM	-1.04.2022		Соп 59 L	nfortDelGro Engineering Pte Ltd oyang Drive Singapore 508969		
То	: _		LKK		F			
Attn			THEVAN		Fax:			
Veh	icle Re	No. : SHA	1388A			10.04.2022		
The	survey	and estimates o	f the repairs of the above-me	entioned vehicle	e are as follow	Ns		
Z	The	repair job shall b	CHINA		SMR6239R			
2.	The	finalized amount	shall be:	- Cillian		3MR0235R		
	(a)		ter List discount					
	(b)	Labour Charge						
			By-Part Repair Cost					
	(c.)	Lumpsum Rep	air (if applicable) sum repair cost after Less:	Therese have presented	~~	\$3,650.00		
 Estimated normal period for repairs: working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 								
5.					We confirm the estimates and finalized amount Signature:			
Name : CHIANG				_	ime :	Thiran		
	Tel : 62148314				ite :	21/4/22		
	Fax	: 6546815	6	_		. ()		
For	Official	Use Only						
		Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks		
1. R	ental Ra	ate P/Day		YES				
		ncome Paid	-	N				
	urvey F		-	· VEC				
5. M	driver,	rch Fee Fees (on behalf if applicable)	\$7.49/\$2.00	YES				
6 O	verrun arks:							

I my su

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO MAKE

SHA1388A

REG. 30.04.2019

10.04.2022

MODEL

MODEL	IONIQ G2	SULANC !	CHINA		
Qty	Parts Description/ Labour	CHIANG/ Type	Unit Price	Amount	
1	FRONT FENDER RETAINER RH/LH	Турс	\$41.40	\$82.80	Mec
1 .	FRONT FENDR RH		, 7 72.10	\$588.80	
1	FRONT FENDER BLUE DRIVE EMBLEM			\$26.60	2.00
1	FRONT FENDER RH SHIELD			\$164.70	
1	FRONT BUMPER COVER			\$481.10	l
1	FRONT BUMPER BRACKET TOP RH/LH		\$35.00	\$70.00	N-C
1	DAY LIGHT RH		Sci	\$642.50)	(Suc
	FRONT BUMPER CLIPS		\$2.20	\$22.00	nec
	FRONT BUMPER MOULDING			\$318.80	5 W
	FRONT BUMPER GRILLE /RH			\$186.20	KSUC
ı	FRONT SUPPORT PANEL			\$949.30	Ksvc
	FRONT HEADLAMP ASSY /RH			\$2,110.30,	KVG
1	FRONT WHEEL COVER RH			\$346.40	SU
	SUB TOTAL			\$5,989.50	
	20.00%			\$1,197.90	
	DISCOUNTED TOTAL		*	\$4,791.60]
					1
					1
					1
	Labour Charge			\$875.00	700
	Panel Beating			\$800.00	500
	Spray Painting Charge			\$90.00	30
	Reset wheel alignment			\$90.00	Brook
	Check Wiring			\$60.00	
	Tuff kote			\$60.00	4
	TOTAL LABOUR	ac s		\$1,975.00	_
				Ţ 1,5 1 5 1 6	+
	ESTIMATE TOTAL	, s		\$ 6,766.60	\exists
				7 2,1 20.00	4
1					-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

82235761 BAII/L//22 1 600 17/17 bfv paint 3clayswp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: