

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0282/2022/NK
DATE : 9-Apr-22
WIP : 19025

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/4/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

9 days exclude 1 Sunday

Johnny Boo - 17 Jun 22

OWNER'S NAME : MR CHIA CHIN SIONG
ADDRESS : 221 UPP PAYA LEBAR RD
#15-02
SINGAPORE 533875
TELEPHONE : HP +65 92318335
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210000310
VEHICLE NO : **SMX 5465 D**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 19/1/2021
ENGINE NO : CZD C22980
CHASSIS NO : WAUZZZF33MI060290
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Apr-22
PLACE OF ACCIDENT : TAMPINES SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 5465 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WAHSE ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$	1,700.00	\$	1,700.00
4	TO CARRY OUT PRESSURISE , VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	\$	1,200.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANIZE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$	2,500.00
6	(Lock carrier replacement - 3 days for Q3) TO RESPRAY FRONT BUMPER, BONNET, HINGE AND BOTH FRONT FENDERS.	\$	4,500.00	\$	1,810.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 14,472.00	\$	8,132.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 5465 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,146.00	\$	1,716.80
2	FRONT BUMPER CONNECTING PIECE	1	\$ 162.00	\$	129.20
3	FRONT BUMPER CLOSING ELEMENT LH / RH	2	\$ 132.00		
4	FRONT BUMPER CENTRE GRILLE	1	\$ 242.00	\$	193.60
5	FRONT BUMPER LOWER COVER	1	\$ 58.00		
6	FRONT BUMPER GRILLE LH / RH	2	\$ 248.00		
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00		
8	FRONT BUMPER SPOILER	1	\$ 426.00	\$	340.80
9	AIR GUIDE GRILLE LH / RH	1	\$ 342.00		
10	RADIATOR GRILLE	1	\$ 1,594.00	\$	1,275.20
11	RADIATOR GRILLE STRIKER PLATE	1	\$ 271.00	\$	216.80
12	RADIATOR GRILLE CAP COVER	1	\$ 47.00		
13	RADIATOR GRILLE BRACKET	1	\$ 46.00		
14	FRONT CAMERA	1	\$ 1,261.00		
15	FRONT BUMPER FOAM	1	\$ 114.00		
16	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 974.00	\$	778.80
17	FRONT BUMPER GUIDE SECTION LH / RH	1	\$ 86.00		
18	FRONT BUMPER TOP COVER	1	\$ 137.00	\$	109.60
19	SIGN 'CAUTION' STICKER	1	\$ 16.00	\$	12.40
20	AIR CON STICKER	1	\$ 9.00	\$	6.64
SUB TOTAL SPARE PARTS		:	\$ 8,523.00	\$	4,779.84

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 5465 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 4,779.84</i>
21	FRONT SENSOR	2	TBC	
22	FRONT SENSOR SEAL RING	4	\$ 10.00	
23	FRONT BUMPER WIRING SET	1	\$ 750.00	
24	SIGNAL HORN HIGH TONE LH	1	\$ 153.00	
25	SIGNAL HORN LOW TONE RH	1	\$ 145.00	
26	SPRING SHACKLE LH / RH	2	\$ 50.00	
27	BONNET	1	\$ 3,695.00	<i>\$ 2,956.00</i>
28	BONNET HINGE LH / RH	2	\$ 162.00	<i>\$ 128.96</i>
29	BONNET ATTACHEMENTS PARTS	1	\$ 309.00	
30	BONNET STRIKER LH / RH	2	\$ 246.00	<i>\$ 196.00</i>
31	SOUND ABSORBER FOR ENGINE BONNET	1	\$ 244.00	
32	IMPACT PROTECTION CENTRE	1	\$ 31.00	<i>\$ 24.24</i>
33	BONNET COVER LH / RH	2	\$ 92.00	
34	PLENUM CHAMBER COVER	1	\$ 144.00	<i>\$ 114.80</i>
35	BOWDEN CABLE CENTER	1	\$ 64.00	<i>\$ 50.56</i>
36	BONNET RELEASE LEVER	1	\$ 16.00	<i>\$ 12.64</i>
37	BONNET COVER	1	\$ 11.00	
38	BONNET LID LOCK CABLE	1	\$ 82.00	
39	BONNET RELEASE ELEMENT	1	\$ 65.00	<i>\$ 51.44</i>
40	BONNET LID LOCK	2	\$ 455.00	<i>\$ 364.00</i>
SUB TOTAL SPARE PARTS		:	\$ 6,724.00	<i>\$ 8,678.48</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 5465 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>8,678.48</i>
41	WHEEL HOUSING LINER FRONT LH	1	\$ 260.00		
42	WHEEL HOUSING LINER FRONT RH	1	\$ 260.00		
43	WHEEL HOUSING LINER ATTACHMENTS FRONT/ REAR	1	\$ 105.00		
44	FRONT FENDER COVER LH / RH	2	\$ 36.00		
45	HEADLIGHT MOUNTING LH / RH	2	\$ 264.00	<i>\$</i>	<i>210.40</i>
46	LED HEADLIGHT	2	\$ 11,904.00	<i>\$</i>	<i>4,761.60</i>
47	LED HEADLIGHT LIFT CYLINDER LH / RH	2	\$ 462.00		
48	LIFT CYLINDER HOSE RH	1	\$ 92.00	<i>\$</i>	<i>73.44</i>
49	LOCK CARRIER MOUNTING	1	\$ 1,412.00	<i>\$</i>	<i>1,129.60</i>
50	AC CONDENSER	1	\$ 605.00	<i>\$</i>	<i>483.60</i>
51	COOLANT	6	\$ 282.00	<i>\$</i>	<i>225.60</i>
52	RADIATOR AIR GUIDE LH / RH	2	\$ 86.00	<i>\$</i>	<i>34.08</i>
53	RADIATOR AIR GUIDE UPPER / LOWER	1	\$ 96.00	<i>\$</i>	<i>37.84</i>
54	COVER	1	\$ 30.00		
55	AIR GUIDE INNER	1	\$ 59.00	<i>\$</i>	<i>46.48</i>
56	AIR GUIDE OUTER	1	\$ 21.00		
57	AIR GUIDE CENTRE	1	\$ 35.00		
58	WHEEL COVER FRONT RH	2	\$ 566.00	<i>\$</i>	<i>452.00</i>
59	WATER DEFLECTOR STRIP LH/ RH	2	\$ 104.00		
60	FRONT NO PLATE	S/N	\$ 60.00	<i>\$</i>	<i>60.00</i>
61	SUNDRIES		400	<i>\$</i>	<i>15.04</i>
TOTAL SPARE PARTS			:	\$ 32,386.00	<i>\$ 16,208.16</i>
TOTAL LABOUR CHARGES			:	\$ 14,472.00	<i>\$ 8,132.00</i>
GRAND TOTAL			:	\$ 46,858.00	<i>\$ 24,340.16</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-26/05/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT