

NEW ZEN WERKZ PTE LTD

BLK 3 KAKI BUKIT RD 1 #03-04 EUNOS TECHNOLINK SINGAPORE 415935

Blk 3 Kaki Bukit Road 1
03 - 04 Eunost Technolink
Singapore 415935

TP Somp
Veron.

13th APRIL 2022

WBAx9120x00x53361

Accident date: 11th APRIL 2022

Estimated repair cost for vehicle no: SND8540T BMW 520I ' 2013 JUNE '

S/n	Qty	Items/Nett	U/price	Amount	
1	1	Front L/H fender <i>Detached</i>		\$1,955.00	✓ 893
2	1	Front L/H headlamp <i>Detached</i>		\$2,150.00	✓ 1466
3	1	Front bumper		\$2,050.00	✗
4	2	Front bumper sensor <i>new</i>	\$210.00	\$420.00	✗
5	10	Front bumper clips <i>new</i>	\$5.00	\$50.00	✓
6	1	Front bumper side retainer -LH <i>new</i>		\$258.00	✗
			Subtotal :-	\$6,883.00	
			4559		
			4103.10		

Labour charges

To remove & Refix front sensor

\$120.00 *50*

To Check Wiring System

\$80.00 *30*

Tuff Kote

\$120.00 *30*

Panel beating

\$600.00 *400*

Spray painting

\$600.00 *400*

Subtotal :- \$1,520.00

Total:- \$8,403.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5013.10

L/S: AK

04 Day