

4 Days.
Lumpsum Repair
After repair photos.
Gino Qiang 82880282
Gino Qiang @ lkk auto. com 18/4/22

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBP3420T

Model : UH200A

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Rear fender / <i>cc</i>		\$ 285.00	199	
2	Rear no plate lamp / <i>S P's</i>		\$ 86.00	60	
3	Rear brake lamp assy / <i>S P's</i>		\$ 490.00	355	
4	Brake lamp lower / <i>n's</i>		\$ 268.00	187	
5	Tail cover / <i>CCP</i>		\$ 220.00	154	
6	Side cowling / <i>CCP</i>		\$ 220.00	154	
7	Exhaust pipe X NN <i>After repair photo.</i> NN	2	\$ 850.00	662	
8	Exhaust end cap / <i>CCP</i>		\$ 680.00	X	
9	Exhaust end cap		\$ 176.00	60	
10	Rear shock absorber <i>BT</i>		\$ 310.00	210	
11	Air box / <i>PR</i>		\$ 280.00	190	
12	Clutch cover / <i>CCP</i>		\$ 350.00	140	
13	Rear wheel rim <i>NN</i>		\$ 390.00	X	
14	Rear foot board (L)		\$ 190.00	✓	
15	Lower panel (L)		\$ 280.00	✓	
16	Bottom cover		\$ 295.00	180	
17	Main stand assy <i>BT</i>		\$ 340.00	158	
18	Front cowling		\$ 520.00	✓	
19	Top cover		\$ 295.00	156	
20	Lower cover		\$ 285.00	150	
21	Front signal lamp <i>NN</i>		\$ 95.00	X	
22	Headlamp assy / <i>CCP</i>		\$ 460.00	420	
23	Front windshield		\$ 370.00	✓	
24	Meter front cover		\$ 193.00	152	
25	Front compartment		\$ 495.00	346	
26	compartment door		\$ 190.00	54	
27	Maintenance cover <i>CCP</i>		\$ 85.00	24	
28	Front fender / <i>CCP</i>		\$ 230.00	145	
29	Handle bar <i>BT</i>		\$ 240.00	128	
30	Handle balancer / <i>CCP</i>		\$ 55.00	25	
31	Rear brake lever		\$ 65.00	35	
32	Mirror / <i>CCP</i>		\$ 98.00	51	
33	Front & rear no plate		5601	\$ 50.00	20
34	Rear box		-10%: 5040.9	\$ 200.00	150
35	Rear tyre <i>NN</i>			\$ 150.00	X
36	ERP IU / <i>CCP</i>			\$ 165.00	✓
37	Side stand extender / <i>CCP</i>			\$ 75.00	20
38	Repair alignment			\$ 380.00	
39	Towing 2 way			\$ 100.00	
39	Labour			\$ 500.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claims must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date:

\$ 9,166.00 \$ 1,620.00 955

\$ 916.60

\$ 8,249.40

5995.9

-20%: 4800

9869.40

600