



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003418/Gvy3e2 Date: 01/07/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 888A	Veh. Inspected	FBP 3420T	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/04/22/2014	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	12/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI UH200A	c.c	200	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MLCC91327K0406293	Colour	GREY	
Odometer	43346 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/90-13	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70-12	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY, FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2022	Inspection Date	18/04/2022	
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	