

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SNE5354D

Make &amp; Model: Mercedes Benz C180

Chassis number: WDD2050402R073082

Date of survey: \_\_\_\_\_

Name of surveyor: \_\_\_\_\_

Contacts: \_\_\_\_\_

| No. | Description of spare parts                            | Qty  | Amount S\$  |     |
|-----|-------------------------------------------------------|------|-------------|-----|
| 1   | Bootlid                                               | 1    | \$ 2,142.75 | pr  |
| 2   | Bootlid centre emblem                                 | 1    | \$ 57.69    | n/c |
| 3   | Bootlid lock                                          | 1    | \$ 278.50   | cur |
| 4   | Bootlid lock catch                                    | 1    | \$ 105.00   | cur |
| 5   | Bootlid weatherstrip                                  | 1    | \$ 215.70   | cur |
| 6   | Rear bumper                                           | 1    | \$ 1,675.44 | cur |
| 7   | Rear bumper clips                                     | 1set | \$ 60.00    | nee |
| 8   | Rear bumper lower garnish                             | 1    | \$ 332.10   | scr |
| 9   | Rear bumper towing cover                              | 1    | \$ 55.60    | scr |
| 10  | Rear bumper lower garnish LH corner reverse sensor    | 1    | \$ 188.10   | cur |
| 11  | Rear bumper lower garnish LH side reverse sensor      | 1    | \$ 188.10   | cur |
| 12  | Rear bumper lower garnish centre LH reverse sensor    | 1    | \$ 188.10   | cur |
| 13  | Rear bumper lower garnish centre RH reverse sensor    | 1    | \$ 188.10   | cur |
| 14  | Rear bumper lower garnish reverse sensor wire harness | 1    | \$ 425.00   | S.C |
| 15  | Rear bumper reverse sensor O-seal                     | 6    | \$ 40.80    | n/c |
| 16  | Rear bumper centre bracket                            | 1    | \$ 167.30   | cur |
| 17  | Rear bumper RH side retainer                          | 1    | \$ 78.00    | nee |
| 18  | Rear bumper LH side retainer                          | 1    | \$ 78.00    | nee |
| 19  | Rear bumper RH bracket                                | 1    | \$ 74.00    | cur |
| 20  | Rear bumper LH bracket                                | 1    | \$ 74.00    | cur |
| 21  | Rear bumper RH lower bracket                          | 1    | \$ 47.70    | cur |
| 22  | Rear bumper LH lower bracket                          | 1    | \$ 47.70    | cur |
| 23  | Rear bumper reinforcement                             | 1    | \$ 710.20   | Di  |
| 24  | Rear bumper kick sensor                               | 1    | \$ 167.00   | cur |
| 25  | Rear bumper kick sensor garnish cover                 | 1    | \$ 118.20   | cur |
| 26  | Rear bumper kick sensor control unit                  | 1    | \$ 373.30   | S.C |
| 27  | Rear bumper lower LH cover                            | 1    | \$ 173.00   | cur |
| 28  | RH taillamp assy                                      | 1    | \$ 766.80   | cur |
| 29  | RH taillamp lower bracket                             | 1    | \$ 76.00    | cur |
| 30  | LH taillamp assy                                      | 1    | \$ 766.80   | cur |
| 31  | LH taillamp lower bracket                             | 1    | \$ 76.00    | cur |
| 32  | End panel                                             | 1    | \$ 1,532.00 | Di  |
| 33  | End panel inner garnish                               | 1    | \$ 188.50   | cur |
| 34  | Spare tyre panel top board                            | 1    | \$ 473.50   | cur |
| 35  | Rear exhaust silencer                                 | 1    | \$ 1,457.80 | cur |
| 36  | Rear exhaust silencer gasket                          | 1    | \$ 55.60    | cur |

|  |  |  |
|--|--|--|
|  |  |  |
|  |  |  |

\$ 13,642.38  
 Parts less 10% \$ 2,728.48  
 Total \$ 10,913.90

| No. | Special Nett Items                     | Amount S\$  |
|-----|----------------------------------------|-------------|
|     |                                        | 450.00      |
| 1   | Rear bumper RH exhaust chrome finisher | 450.00      |
| 2   | Rear bumper LH exhaust chrome finisher | 70.00       |
| 3   | End panel joint sealant                | 1,200.00    |
| 4   | Bootlid spoiler                        |             |
|     | Total:                                 | \$ 2,170.00 |

250  
 SUC  
 4011  
 SUC

| No. | Labour and painting                                                                                                                            | Amount S\$  |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
|     |                                                                                                                                                | 1,500.00    |
| 1   | Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas |             |
|     |                                                                                                                                                | 1,200.00    |
| 2   | Spray painting on affected areas and panels                                                                                                    | 80.00       |
| 3   | Check wiring and lighting system on affected areas                                                                                             | 80.00       |
| 4   | Apply rust coating chemical on affected areas and panels                                                                                       | 120.00      |
| 5   | Remove and replace rear bumper reverse sensors to assist repair                                                                                | 280.00      |
| 6   | Remove and replace rear inner trim and garnish                                                                                                 | 380.00      |
| 7   | Remove and replace exhaust silencer and gasket to assist repair                                                                                |             |
|     | Total:                                                                                                                                         | \$ 3,640.00 |

600

600

30

30

40

70

700

Agreed Amount: 5 days (Part by Part / Lump sum)  
 Working days: 5 days

Thuan@LH444 to low  
 8223 5764

13/4/22 1800

F: L/S 8444 50 8450

RP: 5

Spare Parts: \$ 10,913.90  
 Special Nett: \$ 2,170.00  
 Labour: \$ 3,640.00

Total Amount: \$ 16,723.90

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: