



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@paciflc.net.sg

P91-3

AKW Car Rental.

SLL 8474H

Date 08/4/22 NO.

1.	front bumper torn	\$ 864.00	625 ✓
2	front Head Lamp Assy RH-? XAN	\$ 1214.10	X
3.	front RH bumper Retainer m	\$ 171.75	72.65 ✓
4.	front RH fender Liner cut	\$ 371.45	155.60 ✓
5	front RH fender clip 1 Set m	\$ 50.00	SN 30
6	front RH Road wheel (Sport) Rim	\$ 580.00	SN 350
7	front RH Tyre ? XAN 706	\$ 380.00	SN X
8	front RH Shock Absorber ? XAN	\$ 417.90	X
9	front RH Lower arm ? XAN	\$ 422.18	X
10	front RH Knuckle ? XAN	\$ 571.10	X
11	front RH Knuckle Bearing ? XAN	\$ 230.16	X
12	front LH Road wheel (Sport) Rim	\$ 580.00	SN 350 ✓
13	front LH Shock Absorber ? XAN	\$ 417.90	X
14.	front LH Lower arm ? XAN	\$ 422.18	X
15	front LH Knuckle ? XAN	\$ 571.10	X
16	front LH Knuckle Bearing ? XAN	\$ 230.16	X
17	front LH Tyre ? XAN 706	\$ 380.00	SN X
18	front RH fog Lamp ? XAN	\$ 399.10	X
19	1 Set RH Door Wiser m 120	\$ 150.00	SN 120 ✓
20	Rear RH Door Assy. torn	\$ 1012.00	X
21	Rear RH Dam Regulator ? XAN	\$ 421.20	X
22	Rear RH Door Trim Board ? XAN	\$ 971.10	X

①





bp

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

SLL 8474 H

Date 08/4/22 NO

23	Rear RH Door glass Outer w/strip m/	\$ 271.74	138.40 ✓
24	Rear RH Door w/strip m/	\$ 289.40	176.50 ✓
25	Rear RH Door inner Lock. X n	\$ 571.10	X
26	Rear RH Door Outer handle X n	\$ 178.10	X
27	Rear RH Door Hinges Lower ? X n	\$ 177.30	X
28	Rear RH Door Hinges Top. X n	\$ 187.20	X
29	Rear RH Rocker panel. bt/	\$ 688.45	301.20 ✓
30	front RH Door Assy. bt/	\$ 1217.85	✓
31	front RH Door inner Lock X n	\$ 571.10	X
32	front RH Door w/strip m/	\$ 321.10	215 ✓
33	front RH Door glass Outer w/strip m/	\$ 371.75	149.40 ✓
34	Centre Door pillar RH. repair	\$ 821.22	X
35	front bumper Beam. X n	\$ 465.50	X
36	front RH bumper Beam Bracket. X n	\$ 172.25	X
37	front bumper Sponge. X n	\$ 210.20	X
38	front LH fender Liner. de/	\$ 371.45	155.60 ✓
39	front LH fender Liner Clip 1 set m/	\$ 50.00	SN / 30
		S/N-880	4219.20
			259
			3164.40



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996

TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

AKW Car Rental.

SLL 8474 H

Date 08/4/22 NO.

Labour Charge.

1.	front & Rear RH Door Glass Remove & Refit	\$ 120.00	80
2.	Wiring fee	\$ 50.00	30
3.	Anti Rust	\$ 120.00	80
4.	undercarriage front. Repair & Refit R & L	\$ 400.00	300
5.	wheel alignment	\$ 120.00	80
6.	To Respray Painting Damage Portion	\$ 2000.00	1250
7.	To Repair Acc Damage Portion	\$ 1500.00	1100
8.	Car Seat & interior Remove & Refit.	\$ 150.00	80

Rental

Hp 90010068

11 days

L/S

13/04/22 @ 1630

Resurvey after repair

3164.40

880.00

3000.00

7044.40

20%

5635.52

Repair limit \$3000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date: