

cecilia

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191

Not Authored
Her

2/5 \$ 1500/

13/4/22

Whelp to After repair

2 days.

AXA Insurance Pte. Ltd.

8 Shenton Way

#24-01 AXA Tower

Singapore 068811

Attn: Motor Claims Department

Date: 13 April 2022

**Accident on 05/04/2022 involving vehicles SFX8088Y & SFU14D
along Hougang Avenue 3**

Estimate cost of repair to vehicle SFX8088Y Toyota Camry 2.4A

1 pc.	rear bumper	Re/one	\$	1,033.10	
1 pc.	rear bumper beam	R	\$	488.50	X
1 pc.	rear end panel	R	\$	645.10	X
			\$	2,166.70	
			Less 25%	\$	541.67
				\$	1,625.03

S.Nett Items:

1 set	rear bumper clips	Her	\$	50.00	✓
1 set	rear bumper reverse sensor	short	\$	280.00	200

Labour Charges:

To check wiring	\$	50.00	20
To remove & refix reverse sensor	\$	100.00	50
To remove & refix cushion upholstery	\$	100.00	60
To spray rust proofing	\$	11 100.00	X
Labour for panel beating, welding & renew parts	\$	700.00	400
Spray painting	\$	800.00	400

Total: \$ 3,805.03

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1033.10
257

P-774-82

S.N-250

L-930

1984-82

205

1563