

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 14-Apr-22

MODEL: Mercedes Benz Viano

VEH NO.: SHD 8827M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Insurer: China Taiping

Acknowledged by Repairer

Signature:

Description	Qty	Date	List Price	Amount
Bumper, FRT <i>cut / mounting crack</i>	1		\$ 1,920.00	\$ 1,920.00
Bumper Reinforcement, FRT <i>cut / dent</i>	1		\$ 1,480.00	\$ 1,480.00
Bumper Top Ornamental Cover, FRT <i>HH</i>	1		\$ 370.00	\$ 370.00
Bumper Bracket, FRT/LH <i>mounting broken</i>	1		\$ 136.00	\$ 136.00
Bumper Bracket, FRT <i>HH</i>	1		\$ 133.00	\$ 133.00
Number Plate Trim Cover <i>NR</i>	1		\$ 193.50	\$ 193.50
Head Lamp Assy, (LH/RH) <i>broken / mounting crack</i>	2		\$ 6,638.23	\$ 13,276.46
Head Lamp Panel Assy <i>broken</i>	1		\$ 1,900.00	\$ 1,900.00
Frt Bumper Grille <i>LH mounting crack</i>	1		\$ 440.00	\$ 440.00
Frt Bumper Centre Grille <i>mounting crack</i>	1		\$ 540.00	\$ 540.00
Bonnet Assy <i>Dent</i>	1		\$ 2,760.00	\$ 2,760.00
Bonnet Insulator <i>cut / crumpled</i>	1		\$ 190.00	\$ 190.00
Bonnet Hinge, LH <i>cut</i>	1		\$ 186.76	\$ 186.76
Bonnet Hinge, RH <i>cut</i>	1		\$ 186.76	\$ 186.76
Bonnet Emblem <i>HH</i>	1		\$ 128.50	\$ 128.50
Bonnet Lock Lower <i>Dent / cut</i>	1		\$ 236.80	\$ 236.80
Bonnet Lock Top <i>HH</i>	1		\$ 122.00	\$ 122.00
Bonnet Cable <i>tone / cut</i>	1		\$ 287.22	\$ 287.22
Radiator Grille Star Logo <i>SR</i>	1		\$ 418.78	\$ 418.78
Radiator Grille <i>mounting crack</i>	1		\$ 1,960.00	\$ 1,960.00
Radiator Assy <i>HH</i>	1		\$ 1,250.00	\$ 1,250.00
Radiator Fan Assy <i>HH</i>	1		\$ 1,823.20	\$ 1,823.20
Radiator Fan Coupling Assy <i>HH</i>	1		\$ 1,360.00	\$ 1,360.00
Radiator Fan Top Cover <i>HH</i>	1		\$ 256.00	\$ 256.00
Radiator Side Bracket, LH <i>HH</i>	1		\$ 316.00	\$ 316.00
Radiator Side Bracket, RH <i>HH</i>	1		\$ 316.00	\$ 316.00
Radiator Hose Top <i>HH</i>	1		\$ 79.64	\$ 79.64
Radiator Top Panel <i>HH</i>	1		\$ 638.95	\$ 638.95
Windscreen Glass, FRT with Moulding <i>crack</i>	1		\$ 1,932.68	\$ 1,932.68
Air Cleaner Assy <i>HH</i>	1		\$ 1,238.68	\$ 1,238.68
Fender, FRT/LH <i>Dent</i>	1		\$ 1,320.00	\$ 1,320.00
Fender Top Support, FRT/LH <i>HH</i>	1		\$ 196.74	\$ 196.74
Fender Splash Shield, FRT/LH <i>tone</i>	1		\$ 379.80	\$ 379.80
A/C Condenser <i>HH</i>	1		\$ 1,389.98	\$ 1,389.98
Front Wheel Rim(LH) <i>cut</i>	1		\$ 1,512.00	\$ 1,512.00
Front Wheel Tyre(LH) <i>HH</i>	1		\$ 620.00	\$ 620.00
Frt Wheel Hub & ABS Hub <i>HH</i>	1		\$ 1,965.00	\$ 1,965.00
Frt Fender Housing LH <i>Dent</i>	1		\$ 3,698.88	\$ 3,698.88
Front Stabilizer Bar (LH) <i>HH</i>	1		\$ 838.86	\$ 838.86
Front Stabilizer Bar Link (LH) <i>cut / distorted</i>	1		\$ 136.88	\$ 136.88
Front Stabilizer Bar Bush <i>HH</i>	2		\$ 50.00	\$ 100.00
Front Stabilizer Bar Bracket <i>HH</i>	2		\$ 70.00	\$ 140.00
Front Absorber Mounting <i>HH</i>	1		\$ 338.00	\$ 338.00

✓ 1321.00

✓ 871.00

✗

✓

✗

✗

✓ 9664.00

✓ 833.00

✓ 123.00

✓ 389.00

✓ 2428.00

✓

✓

✓

✓

✓

✗

✓

✗

✓ 788.00

✗

✗

✗

✗

✗

✗

✗

✗

✗

✓

✗

✓ 977.00

✗

✓

✗

✓

✗

✗

✓

✗

✓

✗

✗

✗

✓ 582.10
 ✓ 512.00
 ✓ 631.00
 X
 ✓ 236.00
 ✓ 611.00
 ✓
 ✓
 X
 ✓
 39,232.02
 35,308.81
 X
 40/-
 40.00,
 1200/-
 900/-
 30/-
 40/-
 20/-
 60/-
 180/-
 20/-
 20/-
 20/-
 20/-
 2670.00
 20/-
 20/-
 20/-
 180/-

14/04/222

Hot India

212

14 days.

- Prone 30° before jump

- Check part prices.

- No spare part.
- Need to internet.

7/1 38,018.81