

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22003439/UPA3Q2**Date:** 10/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MFL0001360_03

Claimant Vehicle No : GBJ3327L **Insured Vehicle No :** GBG6404T

Date of Loss: 09/04/2022 Nature of Claim: TP Claim No: MFL2022D0001918

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ3327L**

Make & Model: FORD RANGER, 3.2 (A) Engine No: PJS72443

Reg. Date: 22/03/2019 (Man. Year: 2018) Chassis No: AFAPXXMJ2PJS72443

Colour: Blue Odometer: 47368 km

Engine Capacity: 3198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/50 R20 Rear Tyre Size: 285/50 R20

Front Left Side: RADAR 8 mm Rear Left Side: RADAR 8 mm

Front Right Side: RADAR 8 mm Rear Right Side: RADAR 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,150.60	6,050.48	4,100.12	40.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,260.00	740.00	37.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,150.60	7,310.48	4,840.12	39.83
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	12,150.60	5,800.00	6,350.60	52.27
+ GST 7.00/7.00% (S\$)	850.54	406.00	444.54	52.27
Nett Amount (S\$)	13,001.14	6,206.00	6,795.14	52.27
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
Nett Liability (S\$)		6,741.00		
Global Sum Settlement (S\$)		6,740.00		

INSPECTION

Date of Assignment: 13/04/2022

Date Inspected: 13/04/2022 Inspected At:

Stytech Auto Pte Ltd (kaki Bukit) (HQ)

2 Kaki Bukit Ave 2, #01-03 Kaki Bukit Autohub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 May 2022)	
Parts:	N/A	FORD RANGER 3.2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3327L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,988.30 F	*1,900.00 FL
2	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
3	1		*REAR TAILGATE EMBLEM	Not Necessary	320.00 F	*- FL
4	1		*REAR TAILGATE LIMITED WORDING	Necessary	120.80 F	*120.80 FL
5	1		*REAR TAILGATE RANGER STICKER	Necessary	360.50 F	*360.50 FL
6	1		*REAR TAILGATE INNER GARNISH	Not Necessary	650.80 F	*- FL
7	1		*REAR TAILGATE INNER GARNISH RUBBER	Not Necessary	208.60 F	*- FL
8	1		*LEFT TAILLAMP	Cracked	786.40 F	*600.00 FL
9	1		*LEFT TAILLAMP MOULDING	Cut	186.40 F	*186.40 FL
10	2		*REAR BUMPER (CHROME) LEFT & RIGHT	Dented	1,921.20 F	*1,640.00 FL
11	1		*REAR BUMPER STEP GARNISH	Distorted	1,321.60 F	*1,100.00 FL
12	1		*REAR BUMPER LOWER GARNISH	Cut	380.40 F	*380.40 FL
13	1		*REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*250.00 FS
14	1		*REAR BUMPER INNER SUPPORT	Bent	1,350.40 F	*850.00 FL
15	1		*LEFT REAR FENDER 4X4 STICKER	Necessary	190.20 F	*100.00 FL
					Sub Total (\$\$)	10,150.60 7,498.10
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 1,447.62
					Total Parts (\$\$)	10,150.60 6,050.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	100.00	20.00
2	ANTI RUST PROOF	New	100.00	40.00
3	PANEL BEATING	New	800.00	500.00
4	PAINT WORK	New	1,000.00	700.00
Gross Labour Cost (\$\$)			2,000.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >