

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 20.04.2022
 VEH NO : SMN1174Y
 MODEL : Mercedes B180
 D O A : 11.04.2022
 YR REF : GBD1469E

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMN1174Y (MERCEDES B180)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Dehmed</i>	1	1,458.60 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	170.00 X
3	Rear Bumper Lower Garnish <i>new</i>	1	381.90 X
4	Rear Bumper Top Chrome Moulding <i>new</i>	1	272.60 ✓
			2,283.10
			Less 10% (228.31)
			\$ 2,054.79

S/NETT ITEMS

1	Rear Bumper Clips <i>30</i>	1	\$ 30.00 ✓
	Total Parts		
			\$ 2,084.79

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 400.00 <i>250</i>
2	To putty & spray up paint works	\$ 400.00 <i>250</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To remove reverse sensor	\$ 100.00 <i>50</i>
	Total Labour	
		\$ 950.00

Total Labour

Grand Total

\$ 3,034.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before To remove reverse sensor
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2168.08 (PIP)
03 days