

Auto Insure Pte Ltd (HQ) (Co.Reg.No.201437380M)6 Marsiling Lane
Singapore 739145

Tel: 3157 2626 Fax: 6368 0081 Email: claims01@autoinsure.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	M4738
Policy No:	DMB1SNA00008542101	Date of Loss:	11/04/2022
Vehicle Reg. No.:	PC5592U	Driveable?	YES
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SINGAPORE COACH SERVICES PTE LTD		
Driver:	SHIEH YU		
Make/Model:	KING LONG XMQ6117K, 6.7 (A)	Vehicle Reg. Date:	12/01/2017
Vehicle Colour:	MULTI-COLOUR	Gen Condition:	FAIR
Engine No:	ISB67E528522076980	Chassis No:	LA6R1FSH8GB402380
Odometer:	230090 KM		
Paint Type:	METALLIC 2K		
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	AUTO INSURE PTE LTD (HQ) (WOODLANDS)		

COST OF CLAIMS

	Amount
Parts	77,885.00
Miscellaneous Items	880.00
Labour	7,450.00
Paintwork Labour	1,200.00
Towing	0.00
Calculated Gross Total (S\$)	87,415.00
- Excess (S\$)	2,500.00
(S\$)	84,915.00
+ GST 7.00% (S\$)	5,944.05
Nett Amount (S\$)	90,859.05

This claim is handled by: MARVYN CHUA HONG LENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: (Last Synchronised: 12 Apr 2022)
 Parts: N/A KING LONG XMQ6117K 6.7 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Auto Insure Pte Ltd (HQ)/PC5592U/12/04/2022 16:07
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SIDE MIRROR LH X nn	0.00	0.00	*1,215.00 F X
2	1		*SIDE MIRROR RH X nn	0.00	0.00	*1,215.00 F X
3	1		*FRONT WIPER ARM LH X / cut	0.00	0.00	*139.50 F ✓
4	1		*FRONT WIPER ARM RH X / cut	0.00	0.00	*139.50 F ✓
5	1		*FRONT RH LINKAGE * / DO	0.00	0.00	*1,080.00 F ✓
6	1		*FRONT WINDSCREEN * / OR	0.00	0.00	*3,420.00 F ✓
7	1		*FRONT DRIVER SIDE GLASS part / DO	0.00	0.00	*720.00 F ✓
8	1		*FRONT ROOF PANEL / DO	0.00	0.00	*9,450.00 F ✓
9	1		*FRONT ROOF PANEL INNER TRIM / CRU	0.00	0.00	*8,370.00 F ✓
10	1		*FRONT ROOF PANEL STRUCTURE ? ✓ BT	0.00	0.00	*7,740.00 F ✓
11	1		*CENTER ROOF PANEL / DO	0.00	0.00	*3,780.00 F ✓
12	1		*CENTER ROOF PANEL STRUCTURE ? ✓ BT	0.00	0.00	*2,790.00 F ✓
13	1		*A PILLAR RH / DO	0.00	0.00	*2,520.00 F ✓
14	1		*A PILLAR INNER TRIM RH X nn	0.00	0.00	*1,260.00 F X
15	1		*ROOF AC ASSEMBLY * BR (photo) ? ✓ BR	0.00	0.00	*25,200.00 F ✓
16	1		*ROOF AC ASSEMBLY COVER / BR	0.00	0.00	*3,330.00 F ✓
17	1		*CABIN AC DUCT RH / OR	0.00	0.00	*1,215.00 F ✓
18	1		*CABIN AC DUCT TRIM RH / CRU	0.00	0.00	*648.00 F ✓
19	1		*CABIN AC DUCT TRIM GUIDE RH / CRU	0.00	0.00	*729.00 F ✓
20	1		*ERP BRACKET / OR	0.00	0.00	*26.00 F ✓
21	1		*FRONT WINDSCREEN MOULDING / OR	0.00	0.00	*288.00 F ✓
22	1		*CENTER ROOF PANEL INNER TRIM ? (photo) ✓ CRU	0.00	0.00	*2,610.00 F ✓

F=Franchise part.

Total Parts (S\$)

77,885.00

Supp - * Overhead inner Trim BR - OR

Auto Insure Pte Ltd (HQ)/PC5592U/12/04/2022 16:07. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

74,195.00

07 PM Estimates on Miscellaneous Items Qty Particulars

Repairer Estimates

	Miscellaneous Items	Amount
1	1 AIRCON GAS <i>AK</i>	
2	1 FRONT DRIVER SIDE GLASS SEALANT <i>AK</i>	200.00 ✓
3	1 FRONT WINDSCREEN SEALANT <i>AK</i>	40.00 ✓
4	1 SIDE GLASS SEALANT <i>AK</i>	320.00 ✓
		320.00 ✓
Sub Total (S\$)		880.00 ✓

Estimates on Labour

No Particulars

	Lab.Type	Amount
<u>Paintwork Labour</u>		
1 LABOUR FOR SPRAY PAINTING		
<u>Labour Items</u>		
2 LABOUR FOR PANEL BEATING	New 1000	1,200.00
3 LABOUR TO REMOVE AND REFIT FRONT WINDSCREEN	New 2700	3,000.00
4 LABOUR TO REMOVE AND REFIT DRIVER GLASS	New	800.00 ✓
5 LABOUR TO REMOVE AND REFIT SIDE GLASS	New	200.00 ✓
6 LABOUR TO REMOVE AND REFIT INNER TRIMS	New 1300	1,500.00
7 LABOUR TO REMOVE AND REFIT ROOFTOP AIRCON	New 700	900.00
8 LABOUR TO CHECK WIRING	New	600.00 ✓
9 LABOUR FOR RUSTPROOFING <i>8 Spray Foam</i>	New 200	250.00
	New	200.00 ✓
Gross Labour Cost (S\$)		8,650.00 7700

Auto Insure Pte Ltd (HQ)/PC5592U/12/04/2022 16:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK)
14/4/22, 10:30am

00- M AL
Excess ?
50 dys
M M sy
L/S

82,775.00

L/S - 66,220.00
= 66,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: