

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
AZMAN BIN AHMAD

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	TP/22019
Policy No:		Date of Loss:	10/04/2022
Vehicle Reg. No.:	SNB1580J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	AZMAN BIN AHMAD		
Make/Model:	BMW 320I, 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A)	Vehicle Reg. Date:	30/09/2014
Vehicle Colour:	Metallic Blue/Black		
Engine No:	A356J804N13B16A	Chassis No:	WBA3J92020J642336
Odometer:	110820 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts (after Betterment)	5,026.38
Miscellaneous Items	18.00
Labour	4,150.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	9,194.38
+ GST 7.00% (\$)	643.61
Nett Amount (\$)	9,837.99

This claim is handled by: ANSON SEAH SIEW JOO

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Apr 2022)

Parts: 143 BMW 320I 1.6 EFFICIENT DYNAMICS 2WD NAV HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Car City Auto Centre Pte Ltd/SNB1580J/13/04/2022 13:14

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID	5.00	5	*1,247.30 FL
2	1		*BMW LOGO	5.00	5	*82.15 FL
3	1		*320I EMBLEM	5.00	5	*75.15 FL
4	1		*REAR BUMPER	5.00	5	*1,167.05 FL
5	1		*REAR BUMPER BOTTOM REINFORCEMENT	5.00	5	*95.15 FL
6	1		*REAR BUMPER GUIDE LH	5.00	5	*153.50 FL
7	1		*REAR BUMPER GUIDE CENTER	5.00	5	*153.50 FL
8	1		*REAR BUMPER PROTECTION FOIL LH	5.00	5	*30.75 FL
9	1		*REAR BUMPER REFLECTOR LH	5.00	5	*45.30 FL
10	1		*REAR BUMPER CARRIER	5.00	5	*470.25 FL
11	1		*LH REAR UNDER PANELLING	5.00	5	*71.20 FL
12	1		*TAILLAMP LH	5.00	5	*392.00 FL
13	1		*REAR ULTRA SENSOR LH	5.00	5	*239.25 FL
14	1		*REAR ULTRA SENSOR RING LH	5.00	5	*9.05 FL
15	1		*REAR ULTRA SENSOR WIRE HARNESS	5.00	5	*284.35 FL
16	1		*REAR EXHAUST MUFFLER	5.00	5	*1,025.30 FL
17	1		*REAR EXHAUST MUFFLER MOUNTING	5.00	5	*28.15 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,569.40
- List Item Discount on L Items (\$\$)	278.47

Total Parts (\$\$)	5,290.93
- Betterment (\$\$)	264.55

Total Parts after Betterment (\$\$)	5,026.38
--	-----------------

Car City Auto Centre Pte Ltd/SNB1580J/13/04/2022 13:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	LTA SEARCH FEE	7.00
2	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			18.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO PANEL BEAT,ALIGN,REPLACE BOOT LID,REAR BUMPER,REAR END PANEL,LHR FENDER,REINFORCEMENT AND AFFECTED AREA	Repair	1,200.00
2	TO PUTTY AND RESPRAY PAINT ON BOOT LID,REAR BUMPER,REAR END PANEL,LHR FENDER,REINFORCEMENT AND AFFECTED AREA	Repair	1,500.00
3	TO APPLY TUFF KOTE	Repair	250.00
4	TO REMOVE AND REFIT UPHOISTERY AND SEATS TO ASSIST WORK	Repair	400.00
5	TO REMOVE AND INSTALL ULTRA SENSOR AND WIRING	Repair	200.00
6	TO REMOVE AND INSTALL EXHAUST SYSTEM	Repair	250.00
7	TO RESET FAULT CODE	Repair	250.00
8	TO CHECK WIRING	Repair	100.00
Gross Labour Cost (S\$)			4,150.00

Car City Auto Centre Pte Ltd/SNB1580J/13/04/2022 13:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >