

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

11ST APRIL 2022

GRACE AUTO LEASING
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

TP ALG.
Cedric.

Accident date: 11ST APRIL 2022

Estimated repair cost for vehicle no: SJN1784Y TOYOTA VIOS (A) '2009 COE TIL 2024

S/n	Qty	Items	U/price	Amount
1	1	Front R/H door <i>Distorted</i>		\$1,069.40 ✓
2	1	Front R/H door top hinges <i>new</i>		\$155.20 x
3	1	Front R/H door lower hinges <i>new</i>		\$155.20 x.
4	1	Front R/H door inner trim board <i>new</i>		\$678.20 x
5	1	Front R/H door inner lock <i>new</i>		\$285.20 ✓
6	1	Front R/H door outer handle <i>new</i>		\$185.20 ✓
7	1	Front R/H door inner rubber <i>new</i>		\$261.40 x.
8	1	Front R/H door glass gear <i>new</i>		\$321.20 ✓
9	1	Front R/H door glass gear motor <i>new</i>		\$412.20 x.
10	1	front RH door centre protector <i>new</i>		\$188.20 ✓
11	1	front RH door top moulding / rubber <i>new</i>		\$185.20 ✓
12	1	Rear door center protector RH <i>new</i>		\$158.20 ✓
13	1	R/H door pillar <i>new</i>		\$981.40 x
14	1	Rear R/H door <i>Distorted</i>		\$1,069.40 ✓
15	1	Rear R/H door top hinges <i>new</i>		\$155.20 x
16	1	Rear R/H door lower hinges <i>new</i>		\$155.20 x.
17	1	Rear R/H door inner trim board <i>new</i>		<u>\$675.20</u> 510
18	1	Rear R/H door inner lock <i>new</i>		\$380.80 ✓
19	1	Rear R/H door outer handle <i>new</i>		\$232.55 ✓
20	1	Rear R/H door inner rubber <i>new</i>		\$261.40 x.
21	1	Rear R/H door glass gear <i>new</i>		\$321.20 ✓
22	1	Rear R/H door glass gear motor <i>new</i>		\$422.20 x
23	1	Rear R/H door top moulding / rubber <i>new</i>		\$185.20 ✓
24	1	Rear Tail Lamp-RH <i>new</i>		\$333.70 ✓
25	4	Rear Tail Lamp Clips <i>new</i>	\$6.50	\$26.00 10.
26	1	Rear Bumper <i>new</i>		\$625.20 x
27	8	Rear Bumper Clips <i>new</i>	\$6.50	\$52.00 x
28	1	Rear Bumper Reverse Sensor <i>new</i>		\$350.00 x
29	1	Rear Bumper Bracket <i>new</i>		\$131.70 x
30	1	Rear Bumper Side Reflector -RH <i>new</i>		\$83.10 x
31	1	Rear Fender- RH <i>new</i>		\$972.40 x
32	1	Rear Fender Inner Trim Board-RH <i>new</i>		\$325.10 x
33	10	Rear Fender Inner Trim Board Clips <i>new</i>	\$6.50	\$65.00 x
34	1	Rear tire-RH <i>new</i>		\$350.00 104(SN)
35	1	Rear lower arm -RH <i>new</i>		\$282.20 x
36	1	Rear rim-RH <i>new</i>		\$400.00 ✓
37	1	Rear shock absorber-RH <i>new</i>		\$380.20 x
38	1	Rear bearing-RH <i>new</i>		\$188.20 ✓

Subtotal :-

\$13,459.35

5702.45

4276.83

S.N. 200.

Labour charges

To remove & refit cushion

~~\$120.00~~ ✓

To remove & refit reverse sensor

~~\$100.00~~ 50

to remove & refix rear undercarriage

~~\$200.00~~ 180

To check wiring

~~\$60.00~~ 30

WHEEL alignment (computer)

~~\$120.00~~ 80

Tuff kote

~~\$120.00~~ 80

Panel beating

~~\$1,000.00~~ 800

Spray painting

~~\$1,000.00~~ 900

Subtotal :- \$2,720.00

Total:- \$16,179.35

Adm L
H/S 13/04/22.

06 Days.

total: 6716.83

L/S 5.3k

5.3k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: