

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003447/KVY3Q2**Date:** 16/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00114972102		
Claimant Vehicle No :	SFT79Y	Insured Vehicle No :	GBJ9497P		
Date of Loss:	27/03/2022	Nature of Claim:	TP	Claim No:	SNM22D202123/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFT79Y		
Make & Model:	AUDI S5, 4.2 FSI Quattro Tip (A)	Engine No:	CAU014470
Reg. Date:	23/01/2009 (Man. Year: 2008)	Chassis No:	WAUZZZ8T99A031199
Colour:	Metallic Pearl White	Odometer:	98150 km
Engine Capacity:	4163 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R19	Rear Tyre Size:	275/35Z R19
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 2 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,498.95	3,236.95	2,262.00	41.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	740.00	740.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,978.95	3,976.95	3,002.00	43.02
Approved Total (Overridden) (\$\$)		3,150.00		
(\$\$)	6,978.95	3,150.00	3,828.95	54.86
+ GST 7.00/7.00% (\$\$)	488.53	220.50	268.03	54.86
Nett Amount (\$\$)	7,467.48	3,370.50	4,096.98	54.86

INSPECTION

Date of Assignment:	16/04/2022	
Date Inspected:	13/04/2022 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2022)
Parts:	M1-COUPE	AUDI S5 4.2 FSI Quattro Tip (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFT79Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,840.00 FL	*1,620.00 FL
2	14		*REAR BUMPER CLIPS	Necessary	126.00 FL	*126.00 FL
3	1		*REAR BUMPER CORE	Serviceable	290.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	820.00 FL	*- FL
5	2		*REAR BUMPER SENSORS	Shorted (1 PCS ONLY)	530.00 FL	*265.00 FL
6	4		*REAR BUMPER SENSOR HOLDERS	Necessary	180.00 FL	*180.00 FL
7	1		*REAR BUMPER LOWER DIFFUSER	Cut	620.00 FL	*620.00 FL
8	1		*REAR BUMPER LOWER DIFFUSER MOULDING	Mtg Cracked	460.00 FL	*320.00 FL
9	1		*REAR BUMPER INNER SENSOR CONTROL BOX	Serviceable	360.00 FL	*- FL
10	1		*REAR BUMPER AUTO BOOT SENSOR	Serviceable	265.00 FL	*- FL
11	1		*BOOT EMBLEM (BLACK EDITION)	Necessary	115.00 FL	*115.00 FL
12	1		*BOOT BADGE S5 (BLACK WITH RED WDITON)	Necessary	135.00 FL	*135.00 FL
13	1		*REAR NUMBER PLATE	Necessary	45.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,786.00	3,406.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	287.05	169.05
Total Parts (\$\$)	5,498.95	3,236.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF BOOT ,END PANEL,AND PART REPLACEMENT	New	480.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	440.00
3	TO RESEAL PAINT PROTECTION (DIAMOND RITE) TO SPRAY PAINT AREAS	New	400.00	0.00
Gross Labour Cost (\$\$)			1,480.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >