

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 27.03.2022

Not Notation
L1Pm @ 3150h
Recovery After Repair
3 days

Third Party

Policy No:

12.04.2022

Date:

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Audi S5" Reg. No. SFT79Y Claiming Against Your Insured Veh. No. GBJ9497P			
1pc	Rear Bumper 1820		1,840.00
14pcs	Rear Bumper Clips	9.00	126.00
1pc	Rear Bumper Core		290.00 X
1pc	Rear Bumper Reinforcement		820.00 X
2pcs	Rear Bumper Sensors		530.00
4pcs	Rear Bumper Sensor Holders nec	265.00	1,060.00
1pc	Rear Bumper Lower Diffuser	45.00	180.00
1pc	Rear Bumper Lower Diffuser Moulding P-7 320		620.00
1pc	Rear Bumper Inner Sensor Control Box		460.00
1pc	Rear Bumper Auto Boot Sensor		360.00 X
1pc	Boot Emblem (Black Edition)		265.00 X
1pc	Boot Badge S5 (Black with Red Edition)		115.00
			135.00
	Less 5%		5,741.00
			287.05
			5,453.95
	Rear Number Plate (Cam Type)		45.00 SN
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel And Part Replacement.		480.00 300
	To Respray Affected Areas		600.00 400
	To Reseal Paint Protection (Diamond rite) to Spray Paint Areas		400.00 X
			6,978.95
		Total :	6,978.95