

ASS. REC. BY:

REF: ICS1Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

Munich

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 288k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: OP days

Res.: Yes or No

Lum Sum: 1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SMA 882214 Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia CarensColour: BlackSp. Reading: 332783

Eng/No: \_\_\_\_\_

C/No: KNAHU815VJ721222Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: Greenlander 205/55R16

Duraturn: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 6/18/22

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

ECICS Limited (HQ)

**PARTICULARS OF CLAIM**

|                               |                                   |                       |                   |
|-------------------------------|-----------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                   | Ref. No:              |                   |
| Policy No:                    | MCF22A00000100                    | Date of Loss:         | 06/04/2022        |
| Vehicle Reg. No.:             | SMA8822H                          | Driveable?            |                   |
| Driver Age/Info:              |                                   | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                | Third Party Involved? | YES               |
| Insured/Claimant:             | BIS MOTORING PTE LTD              |                       |                   |
| Make/Model:                   | KIA CARENS, 1.7 D DCT 5DR FWD (A) | Vehicle Reg. Date:    | 06/11/2018        |
| Vehicle Colour:               | BLACK                             | Chassis No:           | KNAHU815VJ7212222 |
| Engine No:                    | D4FDJD028343                      |                       |                   |
| Odometer:                     | 332783 KM                         |                       |                   |
| Paint Type:                   |                                   |                       |                   |
| Total Loss?                   | NO                                |                       |                   |
| Est. Duration of Repair (day) | 8 ✓                               |                       |                   |
| Present Location:             | MUNICH AUTOCARE PTE LTD (HQ)      |                       |                   |

*Not Withheld*  
*I.B.I*  
*Repair B4paint*  
*Ex \$2000/-*

**COST OF CLAIMS**

|                              | Amount    |
|------------------------------|-----------|
| Parts                        | 12,221.00 |
| Miscellaneous Items          | 144.00    |
| Labour                       | 4,690.00  |
| Paintwork Labour             | 0.00      |
| Towing                       | 0.00      |
| Calculated Gross Total (S\$) | 17,055.00 |
| - Excess (S\$)               | 2,000.00  |
| (S\$)                        | 15,055.00 |
| + GST 7.00% (S\$)            | 1,053.85  |
| Nett Amount (S\$)            | 16,108.85 |

This claim is handled by: LEONG CHEE KWONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Apr 2022)  
 Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SMA8822H)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the  
 END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                   | %Disc | %Depr | Amount        |
|-----|-----|----------|-------------------------------|-------|-------|---------------|
| 1   | 1   |          | *front bonnet                 |       |       |               |
| 2   | 1   |          | *front bonnet lock            | 0.00  | 0.00  | ✓ *420.00 F   |
| 3   | 1   |          | *front bonnet insulation      | 0.00  | 0.00  | ✓ *49.00 F    |
| 4   | 1   |          | *front bonnet hinge LH        | 0.00  | 0.00  | ✓ *70.00 F    |
| 5   | 1   |          | *front bonnet hinge RH        | 0.00  | 0.00  | ✓ *25.00 F    |
| 6   | 1   |          | *Front bumper                 | 0.00  | 0.00  | ✓ *25.00 F    |
| 7   | 1   |          | *front radiator grille        | 0.00  | 0.00  | ✓ *350.00 F   |
| 8   | 1   |          | *front bumper top cover       | 0.00  | 0.00  | ✓ *252.00 F   |
| 9   | 1   |          | *front headlamp LH            | 0.00  | 0.00  | ✓ *55.00 F    |
| 10  | 1   |          | *front headlamp RH            | 0.00  | 0.00  | ✓ *880.00 F   |
| 11  | 1   |          | *front headlamp bracket LH    | 0.00  | 0.00  | ✓ *880.00 F   |
| 12  | 1   |          | *front headlamp bracket RH    | 0.00  | 0.00  | ✓ *12.00 F    |
| 13  | 1   |          | *front bumper sponge          | 0.00  | 0.00  | ✓ *12.00 F    |
| 14  | 1   |          | *front bumper Reinforcement   | 0.00  | 0.00  | ✓ *56.00 F    |
| 15  | 1   |          | *front support panel          | 0.00  | 0.00  | ✓ *224.00 F   |
| 16  | 1   |          | *front fender LH              | 0.00  | 0.00  | ✓ *350.00 F   |
| 17  | 1   |          | *front fender RH              | 0.00  | 0.00  | ✓ *220.00 F   |
| 18  | 1   |          | *front inter cooler           | 0.00  | 0.00  | ✓ *220.00 F   |
| 19  | 1   |          | *front a/cond condensor       | 0.00  | 0.00  | ✓ *490.00 F   |
| 20  | 1   |          | *front radiator assy          | 0.00  | 0.00  | ✓ *420.00 F   |
| 21  | 1   |          | *front fan cooling fan coving | 0.00  | 0.00  | ✓ *420.00 F   |
| 22  | 1   |          | *front intake cover           | 0.00  | 0.00  | ✓ *420.00 F   |
| 23  | 1   |          | *front outlet manifold        | 0.00  | 0.00  | ✓ *84.00 F    |
| 24  | 1   |          | *front dash board assy        | 0.00  | 0.00  | ✓ *500.00 F   |
| 25  | 1   |          | *front steering air bag       | 0.00  | 0.00  | ✓ *1,190.00 F |
| 26  | 1   |          | *front passenger air bag      | 0.00  | 0.00  | ✓ *980.00 F   |
| 27  | 1   |          | *front seat belt LH           | 0.00  | 0.00  | ✓ *700.00 F   |
| 28  | 1   |          | *front seat belt RH           | 0.00  | 0.00  | ✓ *280.00 F   |
| 29  | 1   |          | *front seat belt tensioner LH | 0.00  | 0.00  | ✓ *280.00 F   |
| 30  | 1   |          | *front seat belt tensioner RH | 0.00  | 0.00  | ✓ *280.00 F   |
| 31  | 1   |          | *clock spring                 | 0.00  | 0.00  | ✓ *280.00 F   |
| 32  | 1   |          | *air bag computer unit        | 0.00  | 0.00  | ✓ *126.00 F   |
|     |     |          |                               | 0.00  | 0.00  | ✓ *560.00 F   |

F=Franchise part.

|                                     |                  |
|-------------------------------------|------------------|
| Sub Total (\$\$)                    | 11,110.00        |
| + Margin on L,N Items 10.00% (\$\$) | 1,111.00         |
| <b>Total Parts (\$\$)</b>           | <b>12,221.00</b> |

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No Qty Particulars

### Miscellaneous Items

| No               | Qty | Particulars                            | Amount     |
|------------------|-----|----------------------------------------|------------|
| 1                | 6   | FENDER INNER SHIELD CLIP LH            | nn X 42.00 |
| 2                | 1   | FRONT ENGINE COOLANT                   | nn ✓ 25.00 |
| 3                | 6   | FRONT RADIATOR TOP GARNISH CLIPS LH/RH | nn ✓ 42.00 |
| 4                | 1   | FRONT W/SCREEN SEALANT                 | nn X 35.00 |
| Sub Total (\$\$) |     |                                        | 144.00     |

## Estimates on Labour

No Particulars

### Labour Items

| No                       | Particulars                                                                                                                                                                  | Lab.Type | Amount        |
|--------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|---------------|
| 1                        | TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET, BUMPER, SUPPORT PANEL, FENDER LH/RH, WHEEL HOUSE LH/RH CHASSIS LH/RH AND DAMAGE AREA                     | New      | 70d 1,500.00  |
| 2                        | TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION                                                                                                           | New      | 20d 120.00    |
| 3                        | TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS                                                                                                                                     | New      | ✓ 120.00      |
| 4                        | TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA | New      | 60d 350.00    |
| 5                        | TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE                                                                                         | New      | 25d 380.00    |
| 6                        | TO REFILL A/COND GAS                                                                                                                                                         | New      | ✓ 80.00       |
| 7                        | TO CONDUCT 4 WHEEL ALIGNMENT                                                                                                                                                 | New      | nn X 80.00    |
| 8                        | TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND TENSIONER LH & RH, BUCKLE LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH                                             | New      | 220d 380.00   |
| 9                        | TO DISMANTLE & REFIX DASHBOARD, INCLUDING TO REMOVE & REPLACE PASSENGER SEAT AIR BAG AND DRIVER SEAT AIRBAG                                                                  | New      | 25d 480.00    |
| 10                       | TO RESPRAY FRONT PORTION, BONNET INNER / OUTER, FRONT BUMPER, SUPPORT PANEL, FRONT FENDER LH/RH WHEEL HOUSE LH/RH AND POLISH DAMAGE AREAS                                    | New      | 100d 1,200.00 |
| Gross Labour Cost (\$\$) |                                                                                                                                                                              |          | 4,690.00      |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

055D

### Vehicle Details

Vehicle No.:

SMA8822H

Vehicle to be Exported:

No

Intended Deregistration Date:

12 Apr 2022

Vehicle Make:

KIA

Vehicle Model:

CARENS 1.7 DCT DIESEL 5DR FWD

Primary Colour:

Black

Manufacturing Year:

2018

Engine No.:

D4FDJD028343

Chassis No.:

KNAHU815VJ7212222

Maximum Power Output:

104.0 kW (139 bhp)

Open Market Value:

\$20,088.00

Original Registration Date:

07 Nov 2018

First Registration Date:

07 Nov 2018

Transfer Count:

0

Actual ARF Paid:

\$20,124.00

### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

06 Nov 2028

PARF Rebate Amount:

\$15,093.00

### Intended COE Rebate Details

COE Expiry Date:

06 Nov 2028

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$32,311.00

COE Rebate Amount:

\$21,221.00

**Total Rebate Amount:**

**\$36,314.00**

The information contained herein is correct as at 12 Apr 2022

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 08/04/2022 08:57 (SGT)  
Date of Accident ..... 06/04/2022 08:40 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... TPE TOWARDS CTE  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMA8822H

#### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... BIS MOTORING PTE LTD  
Company Reg No ..... 201735055D  
Email Address ..... KEIFTAN@BISMOTORING.COM.SG  
Mobile Phone No ..... (Phone) +65-86881311  
Alternative Phone No ..... +65-86881311

#### VEHICLE PARTICULARS

Manufacturer ..... Kia  
Model ..... Carens  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private hire  
Transmission ..... Auto  
CC ..... 1699


#### INSURANCE COMPANY

Name of Insurance Company ..... ECICS Limited  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... Yes  
Policy Number ..... MCF22A00000100  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... MOHAMMED SAHRIL BIN MASNIN  
NRIC No ..... S8016431I

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 6th of April 2022 @ 0840hrs, I was travelling (SMA8822H) with my gap passenger. At that point the road were dry and clear. Subsequently, I saw the car making a break as such I brake but no able to break on time and my car hit the rear bumper of the front car (SMX6810). I such checked with my passenger and the driver if they had any injuries. However both parties did mentioned that no injuries on them.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 6/4/22

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: