

# Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

**ECICS Limited (HQ)**

## PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)  
Policy No: MCF22A00000100  
Vehicle Reg. No.: **SMA8822H**  
Driver Age/Info:  
TP Injury Involved? NO  
Insured/Claimant: BIS MOTORING PTE LTD

Ref. No:  
Date of Loss: 06/04/2022  
Driveable?  
Party At Fault: UNKNOWN  
Third Party Involved? YES

Make/Model: KIA CARENS, 1.7 D DCT 5DR FWD (A)  
Vehicle Colour: BLACK  
Engine No: D4FDJD028343  
Odometer: 332783 KM

Vehicle Reg. Date: 06/11/2018

Chassis No: KNAHU815VJ7212222

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 8 ✓

*Not Authorised*  
*I.B.I*  
*Mercury B4pam*  
*Ex \$2000/-*

Present Location: MUNICH AUTOCARE PTE LTD (HQ)

## COST OF CLAIMS

	Amount
Parts	12,221.00
Miscellaneous Items	144.00
Labour	4,690.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$)	17,055.00
- Excess (S\$)	2,000.00
(S\$)	15,055.00
+ GST 7.00% (S\$)	1,053.85
Nett Amount (S\$)	16,108.85

This claim is handled by: **LEONG CHEE KWONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 12 Apr 2022)

**Parts:** M1-MPV      KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMA8822H)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*front bonnet 420 ✓	0.00	0.00	R <sub>1</sub> ✓ *420.00 F
2	1		*front bonnet lock 49 ✓	0.00	0.00	DIY ✓ *49.00 F
3	1		*front bonnet insulation	0.00	0.00	DIY ✓ *70.00 F
4	1		*front bonnet hinge LH 25 ✓	0.00	0.00	R <sub>1</sub> ✓ *25.00 F
5	1		*front bonnet hinge RH 25 ✓	0.00	0.00	R <sub>1</sub> ✓ *25.00 F
6	1		*Front bumper 350 ✓	0.00	0.00	CM ✓ *350.00 F
7	1		*front radiator grille 252 ✓	0.00	0.00	CM ✓ *252.00 F
8	1		*front bumper top cover 55 ✓	0.00	0.00	CM ✓ *55.00 F
9	1		*front headlamp LH 880 ✓	0.00	0.00	my car ✓ *880.00 F
10	1		*front headlamp RH 880 ✓	0.00	0.00	✓ *880.00 F
11	1		*front headlamp bracket LH	0.00	0.00	✓ *12.00 F
12	1		*front headlamp bracket RH	0.00	0.00	✓ *12.00 F
13	1		*front bumper sponge 56 ✓	0.00	0.00	CM ✓ *56.00 F
14	1		*front bumper Reinforcement 224 ✓	0.00	0.00	R <sub>1</sub> ✓ *224.00 F
15	1		*front support panel 350 ✓	0.00	0.00	R <sub>1</sub> ✓ *350.00 F
16	1		*front fender LH 220 ✓	0.00	0.00	R <sub>1</sub> ✓ *220.00 F
17	1		*front fender RH 220 ✓	0.00	0.00	R <sub>1</sub> ✓ *220.00 F
18	1		*front inter cooler	0.00	0.00	✓ *490.00 F
19	1		*front a/cond condensor	0.00	0.00	✓ *420.00 F
20	1		*front radiator assy	0.00	0.00	✓ *420.00 F
21	1		*front fan cooling fan coving	0.00	0.00	✓ *420.00 F
22	1		*front intake cover 84 ✓	0.00	0.00	CM ✓ *84.00 F
23	1		*front outlet manifold	0.00	0.00	✓ *500.00 F
24	1		*front dash board assy 400 ✓	0.00	0.00	T <sub>1</sub> ✓ *1,190.00 F
25	1		*front steering air bag 980 ✓	0.00	0.00	ArH ✓ *980.00 F
26	1		*front passenger air bag 700 ✓	0.00	0.00	✓ *700.00 F
27	1		*front seat belt LH 280 ✓	0.00	0.00	J <sub>2</sub> ✓ *280.00 F
28	1		*front seat belt RH 280 ✓	0.00	0.00	J <sub>2</sub> ✓ *280.00 F
29	1		*front seat belt tensioner LH	0.00	0.00	✓ *280.00 F
30	1		*front seat belt tensioner RH 7m ✓	0.00	0.00	✓ *280.00 F
31	1		*clock spring ✓	0.00	0.00	125 ✓ *126.00 F
32	1		*air bag computer unit ✓	0.00	0.00	✓ *560.00 F

F=Franchise part.

Sub Total (S\$) 11,110.00

+ Margin on L,N Items 10.00% (S\$) 1,111.00

Total Parts (S\$) 12,221.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS



## Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	6	FENDER INNER SHIELD CLIP LH	nn X	42.00
2	1	FRONT ENGINE COOLANT	nn ✓	25.00
3	6	FRONT RADIATOR TOP GARNISH CLIPS LH/RH	nn ✓	42.00
4	1	FRONT W/SCREEN SEALANT	nn X	35.00
Sub Total (S\$)				144.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER, SUPPORT PANEL , FENDER LH/RH, WHEEL HOUSE LH/RH CHASSIS LH/RH AND DAMAGE AREA	New	700 1,500.00
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	200 120.00
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New	120.00
4	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA	New	600 350.00
5	TO CONDUCT RE-PROGRAMME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	250 380.00
6	TO REFILL A/COND GAS	New	✓ 80.00
7	TO CONDUCT 4 WHEEL ALIGNMENT	New	nn X 80.00
8	TO DISMANTLE & REFIX FRONT SEAT BELT LH & RH AND TENSIONER LH & RH , BUCKLE LH & RH AND REAR SEAT BELT LH & RH AND BUCKLE LH & RH	New	220 380.00
9	TO DISMANTLE & REFIX DASHBOARD , INCLUDING TO REMOVE & REPLACE PASSENGER SEAT AIR BAG AND DRIVER SEAT AIRBAG	New	250 480.00
10	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , FRONT BUMPER, SUPPORT PANEL , FRONT FENDER LH/RH WHEEL HOUSE LH/RH AND POLISH DAMAGE AREAS	New	1000 1,200.00
Gross Labour Cost (S\$)			4,690.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Date Of Birth	16/06/1980
Occupation	Outdoor
Date Of Driving Pass	03/07/2002
Driving experience	19 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97435724
Alt. Phone Number	-
Email Address	SAHRILMASNIN@GMAIL.COM
Address	674B JURONG WEST STREET 65
Address complement	#02-54
Postcode	642674
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	LESTER 97265259
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMX681D
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	LIN BILAN
NRIC No	S7277280F
Contact Number	(Phone) +65-90227897
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-