

FASTTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

HSR 140 70m

Not Allowed
 Lee

14/4/22
 2/53 4100/
 5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE No: SKP 8247M

| | | | | | |
|------|------------------------------------|--------------|-------------|-------------|---|
| 1PC | TAILGATE | 11 | | \$1,285.00 | X |
| 1PC | TAILGATE REAR LOGO | 11 | | \$145.00 | X |
| 1PC | TAILGATE 'VELOSTER' EMBLEM | 11 | | \$50.00 | X |
| 1PC | TAILGATE WEATHERSTRIP | 11 | | \$299.00 | X |
| 1PC | TAILGATE INNER LOCK | 11 | | \$415.00 | X |
| 1PC | REAR BUMPER | DD | 596.30 | \$1,455.00 | — |
| 1PC | REAR BUMPER CENTRE DIFFUSER | 2e | 365.00 | \$950.00 | — |
| 1PC | REAR BUMPER CENTRE EXHAUST CHROME | Barf | 215.00 | \$480.00 | — |
| 1PC | REAR BUMPER REINFORCEMENT | Cne | 482.00 | \$615.00 | — |
| 2PCS | REAR BUMPER REINFORCEMENT BRACKETS | @\$60.00 11 | | \$120.00 | X |
| 2PCS | REAR BUMPER SIDE RETAINERS | @\$85.00 11 | 48 x 2296 | \$170.00 | — |
| 2PCS | REAR BUMPER PDC SENSORS | @\$225.00 11 | 190 x 22380 | \$450.00 | — |
| 1SET | REAR BUMPER CLIPS | 11 | | \$50.00 | — |
| 1PC | REAR BUMPER LICENCE LAMP | 11 | | \$68.00 | X |
| 1PC | REAR END PANEL | DD | | \$988.00 | — |
| 1PC | REAR END PANEL TOP GARNISH | 7w1 | 522.30 | \$365.00 | — |
| 1PC | TAILLAMP | Cne | 186.20 | \$850.00 | — |
| 1PC | REAR FLOOR PANEL TOP BOARD | 11 | 202 | \$845.00 | X |
| 1PC | REAR FLOOR PANEL | 11 | | \$1,120.00 | X |
| | | | | \$10,720.00 | |

S.NETT

| | | | | |
|------|-------------------------|-------|----------|-----|
| 1PC | REAR LICENCE PLATE | Cne | \$50.00 | 40 |
| 1SET | REAR REVERSE CAMERA | shabb | \$380.00 | 300 |
| 1PC | REAR END PANEL SEALANT | 11 | \$50.00 | ✓ |
| 1PC | REAR WINDSCREEN SEALANT | 11 | \$50.00 | X |

| | | |
|---|-------------|-----|
| TO CHECK WIRING | \$50.00 | 20 |
| TO DISMANTLE & REPLACED REAR PDC SENSOR | \$80.00 | 50 |
| TO DISMANTLE & REFIX REAR WINDSCREEN | \$120.00 | X |
| TO DISMANTLE & REFIX CUSHION UPHOLSTERY | \$120.00 | 80 |
| TO DISMANTLE & REFIX REAR EXHAUST | \$100.00 | 60 |
| TO RESET & DIAGNOSTIC SYATEM | \$280.00 | 50 |
| TO SPARY RUST PROOFING | \$100.00 | 40 |
| LABOUR FOR PANEL BEATING & REPLACED PARTS | \$1,200.00 | 650 |
| TO PUTTY & SPRAY PAINTING | \$1,500.00 | 800 |
| TOTAL | \$14,800.00 | |

P-3742-80
 202
 2994.24
 390
 1750