

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFG 6996D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	1,645.32	-
1	BOOTLID WEATHERSTRIP (CONSISTENT)	TWISTED	197.00	197.00
1	REAR BUMPER (CONSISTENT)	DENTED	1,431.20	1,431.20
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	466.00	466.00
1	REAR BUMPER REINFORCEMENT TOP RETAINER (CONSISTENT)	CRACKED	182.60	182.60
1	REAR BUMPER REINFORCEMENT GARNISH (CONSISTENT)	CRACKED	171.35	171.35
2	REAR BUMPER SIDE HOLDERS @\$105.00 (CONSISTENT)	NOT NECESSARY	210.00	-
1	REAR BUMPER UNDERCOVER (CONSISTENT)	TWISTED	148.50	148.50
2	REAR BUMPER PDC SENSORS @\$198.00 (CONSISTENT)	O/S SHORTED	396.00	198.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR END PANEL (CONSISTENT)	DENTED	945.00	945.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	245.20	245.20
1	TAILLAMP O/S (CONSISTENT)	NOT NECESSARY	645.00	-
	LESS 10% DISCOUNT		-	-403.49
			6,733.17	3,631.36
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO RESET & DIAGNOSTIC SYSTEM.		120.00	50.00
	TO SPRAY RUST PROOFING.		100.00	40.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID.		1,080.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
			2,850.00	1,640.00
	GRAND TOTAL		9,583.17	5,271.36

Report Ref No. CS/ASM22003456/Uqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22003456/Uqy3e2

CHUA KANG SENG

Licensed Appraiser