

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ASM22003456/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFG 6996D

at Workshop m/s

Biml

of

Insured:

EM1881P

Policy No.

Claims No.

32M03YK2

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

44k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

403f

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 32531

Veh No: SFG 6996D

Yr Regn:

07/06/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

BMW 520i

c.c

1997

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

157451

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W3AXG12020D29/300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45 R18

R:

245/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/4/22

D.O.I.

22/4/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Ref / 19k

Coe until 06-06-2023

28/4/22 4/5 @ 4200 informed Kenny (red 3383.17, 567)

28/4/22 @ 12.00pm revised to Cynthia Lok via ~~TP~~ Smart Claims.

Date/Time, File Pass to?

☐

: Preli. Report

1) 28/4/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format:

Smart Claims-TP

Lump Sum / I.B.I. (\$

4200

)

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/53/55/56
SINGAPORE 417883 TEL :67452088

not Authorized
Hills
merous
22/4/22
1/54 4200
H d n y s.

VEHICLE No: SFG 6996D

1PC	BOOTLD
1PC	BOOTLID WEATHERSTRIP
1PC	REAR BUMPER
1PC	REAR BUMPER REINFORCEMENT
1PC	REAR BUMPER REINFORCEMENT TOP RETAINER
1PC	REAR BUMPER REINFORCEMENT GARNISH
2PCS	REAR BUMPER SIDE HOLDERS @\$105.00
1PC	REAR BUMPER UNDERCOVER
2PCS	REAR BUMPER PDC SENSORS @\$198.00
1SET	REAR BUMPER CLIPS
1PC	REAR END PANEL
1PC	REAR END PANEL TOP GARNISH
1PC	TAILLAMP O/S

R	\$1,645.32	X
twi	\$197.00	/
rr	\$1,431.20	/
rr	\$466.00	/
cu	\$182.60	/
cu	\$171.35	/
rr	\$210.00	X
twi	\$148.50	/
1/s	\$396.00	1/c
rr	\$50.00	/
rr	\$945.00	/
twi	\$245.20	/
rr	\$645.00	X
	\$6,733.17	

102

TO CHECK WIRING
TO DISMANTLE & REPLACED REAR PDC SENSOR
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO RESET & DIAGNOSTIC SYSTEM
TO SPRAY RUST PROOFING
TO TRANSFER BOOTLID MECHANISM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
	\$80.00	50
	\$120.00	80
	\$120.00	50
	\$100.00	40
^^	\$100.00	X
	\$1,080.00	600
	\$1,200.00	800
TOTAL	\$9,583.17	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 4034-85
102
7-3631-36
2-1640.00
5271.36
202
4217