



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: WINNIE HO			Ref: CS/ASM22003457/Aty3s2 Date: 26/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 9459G	Veh. Inspected	SLV 4693R	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M03YKN	Excess (\$)	0.00	
Assign From	HO Winnie	Assign Date	14/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA SIENTA HYBIRD	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	NHP1707105869	Colour	RED	
Odometer	303321 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	FIRENZA	6 mm	
L/H Front Tyre	185/60 R15	FIRENZA	6 mm	
R/H Rear Tyre	185/60 R15	FIRENZA	6 mm	
L/H Rear Tyre	185/60 R15	FIRENZA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/04/2022	Inspection Date	14/04/2022	
Survey held at	2020 SPRAY PAINTING PTE LTD 53 UBI AVENUE 1, #05-15, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	