

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 02 Nov 2022

Preliminary Advice

Insured : YP9045G
Vehicle No
TP Vehicle : SH6616S Accident Date : 09/04/2022
No
Make : HYUNDAI AE IONIQ HEV FL Assignment Date : 14/04/2022
Date of : 18/04/2022 Est. Duration of : 16
Inspection Repair
Inspection At : BIFROST AUTO PTE LTD (SIN MING) (HQ)
BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 57,913.16
Revised Amount	:S\$ 41,316.28
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ 41,316.28

Lump Sum Repair	:S\$ 33,000.00
-----------------	----------------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.