

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 25 Apr 2022

Preliminary Advice

Insured : CB7227X
Vehicle No
TP Vehicle : SFD55A Accident Date : 13/04/2022
No
Make : TOYOTA VELLFIRE Assignment Date : 14/04/2022
Date of : 14/04/2022 Est. Duration of : 4
Inspection Repair
Inspection At : POON SIANG SEOW (HQ)
160 SIN MING DRIVE, #05-13 SIN MING AUTOCITY
SINGAPORE 575722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,949.40
Revised Amount	:S\$	4,976.33
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,976.33

Lump Sum Repair	:S\$	3,950.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.