

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Re	ef: CS/FCI22003460/Uqy3e2	
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877	Da	te: 23/05/2022	
			Co	ode: FCI2	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 151K	Veh. Inspected	SKF 7277K	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D22001073MFCV	Excess (\$)	0.00	
	Assign From	HARMINDER KAUR	Assign Date	14/04/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALPHARD (A)	c.c	2362	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	ANH208231214	Colour	WHITE	
	Odometer	119844 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/40Z R19	MICHELIN	6 mm	
	L/H Front Tyre	245/40Z R19	MICHELIN	6 mm	
	R/H Rear Tyre	245/40Z R19	MICHELIN	6 mm	
	L/H Rear Tyre	245/40Z R19	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/04/2022	Inspection Date	14/04/2022	
	Survey held at	TICK HAI MOTOR & WELDING	SERVICES		
		BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKI SINGAPORE 417883	Т		
5a. Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days			