

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0159/2022/JT
DATE : 11-Mar-22
WIP : 15362

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 16/3/22**YOUR INSURED VEH NO : SGD 51 Z****AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TOH WEI LIN
ADDRESS : 28 SCOTTS ROAD
#02-01
SINGAPORE 228223
TELEPHONE : HP +65 96268655
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070030798-01
VEHICLE NO : SGD 51 Z
MODEL CODE : AUDI Q5 2.0 TFSI QU
MODEL YEAR : 27/2/2020
ENGINE NO : DAX 060243
CHASSIS NO : WAUZZZFYXK2138776
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Mar-22
PLACE OF ACCIDENT : FAR EAST SHOPPING CENTRE CAR PARK C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage (parts) during resurvey
- Parts prices shall subject to confirmation
- Third party survey is only without "Pre-udnet" basis
- No illegal modification is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGD 51 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASY AND FRONT PARKING AID	S/N \$ 480.00	/ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	/ 250
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	1000 ✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,500.00	1600 ✓
5	TO APPLY PAINT COATING ON AFFECTED AREA. (BY OWNER)	S/N \$ 253.00	/ ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 8,625.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGD 51 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER X Repair	1	\$ 1,680.00	
2	FRONT BUMPER FIXING PARTS X	1	\$ 338.00	
3	FRONT BUMPER SECURING STRIP - LH X	1	\$ 42.00	
4	FRONT BUMPER CLOSING ELEMENT - LH X	1	\$ 126.00	
5	FRONT BUMPER SPOILER X	1	\$ 850.00	
6	FRONT BUMPER CLOSING ELEMENT X	1	\$ 246.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH X	1	\$ 651.00	
8	FRONT BUMPER END CAP - LH X	1	\$ 103.00	
9	LOCKING CLIP X	2	\$ 9.00	
10	FRONT BUMPER GUIDE SECTION - LH X NN	1	\$ 43.00	
11	FRONT BUMPER TOP COVER X	1	\$ 144.00	
12	CAUTION STICKER X	1	\$ 16.00	
13	AIR COND STICKER X	1	\$ 22.00	
14	BONNET BT	1	\$ 4,280.00	3424
15	BONNET ATTACHMENT PARTS X	1	\$ 147.00	
16	BONNET STRIKER - LH X	1	\$ 134.00	
17	BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$ 93.00	73.2
18	BONNET LOCK MICRO-SWITCH X NN	1	\$ 228.00	
19	HEADLIGHT MOUNTING - LH X NN	1	\$ 132.00	
20	HEADLIGHT - LH / CPA	1	\$ 8,708.00	6966.4
SUB TOTAL SPARE PARTS		:	\$ 17,992.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGD 51 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT CONTROL UNIT X NN	1	\$ 813.00	
22	HEADLIGHT HEAT SINK - LH X NN	1	\$ 1,222.00	
23	HEADLIGHT POWER MODULE - LH X NN	1	\$ 850.00	
24	HEADLIGHT HOSE - LH X	1	\$ 45.00	
25	LIFT CYLINDER - LH X	1	\$ 153.00	
26	LIFT CYLINDER HOSE - LH X	1	\$ 145.00	
27	FRONT WHEEL SPOILER - LH X	1	\$ 181.00	
28	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,418.00	1134.4
29	SUNDRIES X NN		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 23,119.00	
TOTAL LABOUR CHARGES		:	\$ 8,625.00	
GRAND TOTAL		:	\$ 31,744.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	<i>Mr. Qial</i>
SURVEYED DATE	:	
AUTHORISED DATE	:	<i>13/4/22</i>
EXCESS COST	:	
LIABILITY	:	
REMARKS	:	<i>Not Authorized. before patrol photos.</i>
PLEASE NOTE	:	THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

Wong S.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT