

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003465/GNCE2**Date:** 15/11/2022REFERENCE

Insured/Claimant:	LEE SEE THONG	Policy No:	7210052041	
Date of Loss:	09/04/2022	Nature of Claim:	OD	Claim No: 2578392542SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP832B	Engine No:	DFY273230
Make & Model:	AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)	Chassis No:	WAUZZZGY0MA104269
Reg. Date:	24/05/2021 (Man. Year: 2021)	Odometer:	13644 km
Colour:	Grey		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,127.80	5,854.88	10,272.92	63.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,212.00	3,457.00	7,755.00	69.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,339.80	9,311.88	18,027.92	65.94
+ GST 7.00/7.00% (S\$)	1,913.79	651.83	1,261.96	65.94
Nett Amount (S\$)	29,253.59	9,963.71	19,289.88	65.94

INSPECTION

Date of Assignment:	14/04/2022		
Date Inspected:	13/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,914.00 FS	*1,531.20 FS
2	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	32.00 FS	*- FS
3	1		*REAR BUMPER TRIM - LH	Cut	72.00 FS	*56.96 FS
4	1		*REAR PARKING AID SENSOR SUPPORT - LH OUTER	Not Necessary	28.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Cut	226.00 FS	*180.40 FS
6	1		*RETAINER CONTROL UNIT	Not Necessary	28.00 FS	*- FS
7	1		*TAILGATE SENSOR LINE	Not Necessary	228.00 FS	*- FS
8	1		*REAR LIGHT REFLECTOR - LH	Cracked	37.00 FS	*29.36 FS
9	1		*TAIL LIGHT OUTER - LH	Not Necessary	1,049.00 FS	*- FS
10	1		*TAIL LIGHT INNER - LH	Not Necessary	776.00 FS	*- FS
11	1		*TAIL LIGHT INNER TRIM - LH	Not Necessary	30.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	599.00 FS	*478.80 FS
13	2		*REAR BUMPER REINFORCEMENT BEAM BRACKET - LH / RH	Not Necessary	63.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - LH	Broken	62.00 FS	*49.44 FS
15	1		*REAR PARKING AID SENSOR - OUTER	Cut	194.80 FS	*194.80 FS
16	6		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	48.00 FS	*- FS
17	1		*SET REAR BUMPER WIRING	Not Necessary	449.00 FS	*- FS
18	1		*AERIAL RETAINER - LH	Bent	29.00 FS	*22.48 FS
19	1		*TAIL LIGHT OUTER TRIM - LH	Not Necessary	34.00 FS	*- FS
20	1		*TELEPHONE AERIAL - LH	Broken	192.00 FS	*153.60 FS
21	1		*AERIAL FOR KESSY	Not Necessary	78.00 FS	*- FS
22	1		*REAR LID	Bent	3,657.00 FS	*2,925.60 FS
23	1		*REAR LID ATTACHMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
24	2		*REAR LID HINGE - LH / RH	Not Necessary	458.00 FS	*- FS
25	1		*REAR LID FLAP GASKET	Not Necessary	229.00 FS	*- FS
26	1		*REAR LID LOCK	Not Necessary	217.00 FS	*- FS
27	1		*REAR LID LOCK FLAP COVER CAP	Not Necessary	8.00 FS	*- FS
28	1		*REAR LID LOCK STRIKER	Not Necessary	73.00 FS	*- FS
29	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
30	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
31	1		*A3 EMBLEM	Necessary	104.00 FS	*82.80 FS
32	1		*REAR END PANEL	Not Necessary	345.00 FS	*- FS
33	1		*REAR END PANEL REINFORCEMENT	Not Necessary	1,407.00 FS	*- FS
34	2		*REAR END PANEL CONNECTING PLATE - LH / RH	Not Necessary	264.00 FS	*- FS
35	1		*REAR END PANEL TRIM	Not Necessary	171.00 FS	*- FS
36	1		*REAR VENT TRIM - LH / RH	Not Necessary	75.00 FS	*- FS
37	1		*REAR SILENCER	Not Necessary	812.00 FS	*- FS
38	2		*EXHAUST SYSTEM RETAINER	Not Necessary	94.00 FS	*- FS
39	1		*REAR SILENCER DUAL CLIP	Not Necessary	66.00 FS	*- FS
40	1		*REAR SILENCER HEAT SHIELD	Not Necessary	180.00 FS	*- FS
41	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
42	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
43	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
44	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
45	1		*SUNDRIES	Necessary	400.00 FS	*17.92 FS
46	1		*BOOT LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 16,127.80 5,854.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR LHS TAILLAMP PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,500.00	1,250.00
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING. SPARE WHEEL HOUSING AND LHS TAILLAMP PANEL	New	4,000.00	1,375.00
6	TO RENEW REAR EXHAUST SILENCER. TO ALIGN TO POSITION	New	480.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,212.00	3,457.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >