



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 1066U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | RH REAR DOOR (N) | BENT | 899.00 | 899.00 |
| 1 | SET RH REAR DOOR BLACK TAPE (N) | NECESSARY | 56.00 | 56.00 |
| 1 | RH REAR FENDER (N) | TO REPAIR SEE LABOUR | 723.00 | - |
| 1 | REAR BUMPER (N) | TO REPAIR SEE LABOUR | 708.00 | - |
| 1 | SPORTS RIM (N) | DENTED | 710.00 | 708.00 |
| | LESS 10% DISCOUNT | | -309.60 | -166.30 |
| | | | 2,786.40 | 1,496.70 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SEALANT (SN) | NOT NECESSARY | 45.00 | - |
| 12 | REAR BUMPER CLIPS @\$3.00 (SN) | NOT NECESSARY | 36.00 | - |
| 1 | REAR WINDSCREEN GLASS INNER SEAL (SN) | NOT NECESSARY | 80.00 | - |
| | | | 161.00 | - |
| | <u>LABOUR</u> | | | |
| | TO REMOVE/REFIX REAR WINDSCREEN GLASS. | NOT NECESSARY | 120.00 | - |
| | TO TRANSFER LH AND RH REAR DOOR MECHANISM. | | 100.00 | 60.00 |
| | TO REFIT REVERSE SENSOR IN NEW BUMPER. | NOT NECESSARY | 50.00 | - |
| | TO APPLY BODY SEALANT TO CAR JOINTS. | NOT NECESSARY | 150.00 | - |
| | TO RUST PROOF ACCIDENT DAMAGE AREA. | | 150.00 | 50.00 |
| | TO REMOVE/REFIX TRIMS,SPEAKERBOARD,SEATS,ETC. | NOT NECESSARY | 200.00 | - |
| | TO CUT OUT/REWELD RH REAR FENDER,REPAIR INNER PANEL INCLUDING REPLACEMENT OF PARTS.INCLUSIVE OF THE REPAIR OF RH REAR FENDER AND REAR BUMPER. | | 800.00 | 500.00 |
| | TO SPRAY PAINTING ON RH REAR DOOR,RH REAR FENDER INNER/OUTER,REAR BUMPER,REAR END PANEL. | | 1,000.00 | 600.00 |
| | | | 2,570.00 | 1,210.00 |
| | GRAND TOTAL | | 5,517.40 | 2,706.70 |

Report Ref No. CS/AGI22003469/Kqy3n2



| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 2,150.00 |
|---|--|--|-----------------|

Report Ref No. CS/AGI22003469/Kqy3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.