

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0097/2022  
DATE : 13-APR-2022

ALLIANZ INSURANCE SINGAPORE PTE LTD  
79 ROBINSON ROAD #09-01

S(068897)  
TEL : 63954779/67143369  
FAX : 63953768  
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : TENG SOO THENG @MRS TAN SHOOEE  
ADDRESS : 17 CHUAN VIEW

S(554753)  
TELEPHONE NO : 93368228/91463488

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-XD8367J  
VEHICLE NO : SMF9229M  
MODEL CODE : TDWARDZE12EDAY520Z  
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018  
ENGINE NO : HR12244998J  
CHASSIS NO : JN1TAAE12Z0982419  
MILEAGE : 1 KM  
DATE IN : 13/04/2022  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 12/04/2022

*12/11/2022*  
*13/04/2022*

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

*Click*  
*and Print*  
*YAT Lee*  
*6741246*  
*Apr*  
*new*  
*10/4*

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF9229M

| S/NO JOB CODE        | NATURE OF JOB                                                        | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------------------------------------------------------------------|-------------------|---------------------------|
| 1 SEALI              | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA   | 100.00            | / ✓                       |
| 2 WD42               | CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE | 108.00            | / ✓                       |
| 3 ZZ/001             | REPAIR FRONT BUMPER AND RENEW RH FRONT FENDER 390                    | 800.00            | 585 ✓                     |
| 4 ZZ/002             | S/PAINT FRONT BUMPER AND RH FRONT FENDER                             | 750.00            | 500 ✓                     |
| 5 ZZ/003             | RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING                     | 15.00             | / ✓                       |
| 6 ZZ/004             | SUPPLY AND RENEW RH FRONT TYRE CONTI 185/65R15                       |                   |                           |
| TOTAL LABOUR CHARGES |                                                                      | 1773.00           |                           |

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF9229M

|                                                       |              | DAMAGED PARTS & PRICES |      |                            |
|-------------------------------------------------------|--------------|------------------------|------|----------------------------|
| S/NO PARTS DESCRIPTION                                | PARTS NUMBER | NETT                   | LIST | S/NETT REMARKS             |
| 1 ALLOY RIM RH FRONT S/RIM <i>/ Ser</i>               | 40300-0SK92  |                        |      | 280.00 ✓                   |
| 2 CANOE RIVET FENDER \$7.70 EA X 03 <i>/ 5 ac</i>     | 76882-0M000  | 23.10                  | ✓    |                            |
| 3 CLIP FENDER \$1.40 EA X 14 <i>/</i>                 | 01553-05933  | 19.60                  | ✓    |                            |
| 4 PROTECTOR-FR, RH <i>? X nn</i>                      | 63842-3VA0A  | 108.40                 |      |                            |
| 5 FENDER-FRONT RH <i>/ Bue</i>                        | F3100-5VAMA  | 587.30                 | ✓    |                            |
| 6 SUNDRIES <i>/ MLC</i>                               | NPN          |                        |      | 20.00 ✓                    |
| 7 185/65R15 CONTI RH FRONT <i>/ TN</i>                | TYRE         |                        |      | 165.00 <i>-20%<br/>132</i> |
| SUB TOTAL                                             |              | 738.40                 | 0.00 | 465.00                     |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |              | 147.68                 | 0.00 | 0.00                       |
| GRAND TOTAL                                           |              | 590.72                 | 0.00 | 465.00                     |
| OVERALL TOTAL                                         |              | 1055.72                |      |                            |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF9229M

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 1773.00   |
| TOTAL SPARE PARTS CHARGES | 1055.72   |
| GRAND TOTAL               | 2828.72 * |

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

|                 |        |
|-----------------|--------|
| NAME            | :      |
| SURVEYED DATE   | :      |
| AUTHORIZED DATE | :      |
| EXCESS CLAUSE   | : 0.00 |
| LIABILITY       | : 0.00 |
| REMARKS         | :      |

*Guo Qiang*  
*18/4/22*

*3 Days.*

*before periot photo S.*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: