

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0097/2022
DATE : 13-APR-2022

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)
TEL : 63954779/67143369
FAX : 63953768
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : TENG SOO THENG @MRS TAN SHOOEE
ADDRESS : 17 CHUAN VIEW

S(554753)
TELEPHONE NO : 93368228/91463488

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-XD8367J
VEHICLE NO : SMF9229M
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12244998J
CHASSIS NO : JN1TAAE12Z0982419
MILEAGE : 1 KM
DATE IN : 13/04/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 12/04/2022

12/11/2022
13/04/2022

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

Click
and Print
YAT Lee
6741246
Apr
new
LOB

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMF9229M

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	/
2 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	108.00	/
3 ZZ/001	REPAIR FRONT BUMPER AND RENEW RH FRONT FENDER 390	800.00	585
4 ZZ/002	S/PAINT FRONT BUMPER AND RH FRONT FENDER	750.00	500
5 ZZ/003	RENEW RH FRONT S/RIM AND CONDUCT WHEEL BALANCING	15.00	/
6 ZZ/004	SUPPLY AND RENEW RH FRONT TYRE CONTI 185/65R15		
TOTAL LABOUR CHARGES		1773.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMF9229M

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 ALLOY RIM RH FRONT S/RIM <i>/ Ser</i>	40300-0SK92			280.00
2 CANOE RIVET FENDER \$7.70 EA X 03 <i>/ 5 ac</i>	76882-0M000	23.10		
3 CLIP FENDER \$1.40 EA X 14 <i>/</i>	01553-05933	19.60		
4 PROTECTOR-FR, RH <i>? Bue</i>	63842-3VA0A	108.40		
5 FENDER-FRONT RH <i>/ Bue</i>	F3100-5VAMA	587.30		
6 SUNDRIES <i>/ MLC</i>	NPN			20.00
7 185/65R15 CONTI RH FRONT <i>/ TN</i>	TYRE			165.00 - 20%
SUB TOTAL		738.40	0.00	465.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		147.68	0.00	0.00
GRAND TOTAL		590.72	0.00	465.00
OVERALL TOTAL		1055.72		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMF9229M

TOTAL LABOUR CHARGES	1773.00
TOTAL SPARE PARTS CHARGES	1055.72
GRAND TOTAL	2828.72 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Guo Qiang
18/4/22

3 Days.

before periot photo S.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: