



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

Finalization

# ESTIMATE FOR SNC8314K

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Steve

## Vehicle & Document Information

WIP No 56167  
Reg No/Reg Date SNC8314K / 19/11/2021  
Date In/Mileage 25/04/2022/ 6107  
Chassis No W1N2477842J3370375  
Engine No 28291480689304  
Make/Model MB/GLA 180  
Colour/Trim 027 787 Mountain Gt/ 041 101 ARTICO Blac

| Account No                      | Terms  | Date/Time Printed | CSE | Operator               |            |       |        |
|---------------------------------|--------|-------------------|-----|------------------------|------------|-------|--------|
| WC000668                        | Credit | 27/07/2022/ 18:22 | AQ  | 305 / Alan Quek Ai Lun |            |       |        |
| Description of Goods / Services |        |                   |     | Qty                    | Unit Price | Disc% | Amount |

M BPNSUN  
POLICY NO/ACC DATE : 7210140177 // 08-04-2022  
DRIVE IN: 13-04-2022 // TP CAR NO: SKW1260H (CHINA TAIPING INS)  
DATE IN/DATE SURVEY: 25-04-2022 // LKK STEVE  
BY/AUTHORIZED ON : ADELINE CHNG // 14-04-2022  
A BPILAB  
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO  
STANDARD SETTINGS.NETT  
A BPILAB  
REPAIR REAR RIGHT DOOR SHELL  
A BPIRES  
RESpray REAR RIGHT DOOR

0.10 380.00  
0.05 800.00

3 Days

ESTIMATE

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett** 1,660.00  
116.20  
**Total Payable** 1,776.20

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG