

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 41792

Email: ryderautoworkshop@gmail.com  
Tel: 67418277 Fax: 67468277

JTEGH23340002787

## ESTIMATE OF REPAIR

Veh# SLV1610A

TP Budget Direct.  
veron

Model: TOYOTA PICNIC

Accident Date 10/4/2022

4/1/2010

Location BLK 601 HDB CLEMENTI WEST CARPARK

3P: SJH20125 (ALLIANZ)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Red</i>	<del>870.40</del>	586	
2	10 pcs	Rear bumper clips <i>Red</i>		40.00	
3	1 pc	Rear bumper n/s retainer <i>Red</i>	106.20	X	
4	1 pc	Rear bumper n/s reflector <i>Red</i>	128.20	+	
5	1 set	Rear bumper reverse sensor <i>Red</i>		280.00	<i>200</i>
6	1 pc	Rear tail gate <i>Red</i>	<del>2,252.40</del>	1267	
7	12 pc	Rear tail gate inner trim clips <i>Red</i>		48.00	
Sub Total:			3,357.20	368.00	0.00
			25%	0%	0%
After Less %:			2,517.90	368.00	0.00

Labour			
1	To dismantle, straighten & welding.		600.00 <i>400</i>
2	To spray painting.		600.00 <i>400</i>
3	To remove & refit rear windscreen.	<i>1060</i>	160.00 <i>120</i>
4	To remove & replace rear reverse sensor.		60.00 <i>50</i>
5	To check wiring.		50.00 <i>30</i>
6	To remove and replace rear tail gate <i>fitting</i>		100.00 <i>60</i>
Sub Total:			1,570.00
Total:			4,455.90
After Less 20%:			3,564.72

*Chan*

Chan San Choon  
Director  
DipEng, AAE MIMI, MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Adnan*  
*1/5 18/04/22.*  
*03 days.*  
*total: 2649.75*  
*1/5: 2.1K.*

