

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

M/S : Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Claim No :

No :

Date : 14/04/2022

Policy No : SP2000900490

Veh Reg No : SGR9909S

Make / Model : Hyundai Elantra

Chassis No : KMHDH41CMCU215681

Engine No :

Reg. No :

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 22/AL/OD-181 (04)
Claim Type : OD CLAIM
Accident Date : 12/04/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

ESTIMATE FOR VEHICLE NO: SGR9909S

Discription	Quantity	List Price	Amount
Cost Price		S\$	S\$
1 FRT BONNET ✓ BUC	1 PC	\$480.00	
2 FRT BONNET HINGE ?	2PCS	\$60.00	
3 FRT BONNET LOCK ✓ BT	1 PC	\$38.00	
4 FRT GRILLE ASSY ✓ CUT	1 PC	\$105.00	
5 FRT GRILLE CLIP ✓ NEC	4PCS	\$8.00	
6 FRT BUMPER ✓ CRA	1 PC	\$295.00	
7 FRT BUMPER RETAINER X NN	2PCS	\$24.00	
8 FRT BUMPER CLIP ✓ NEC	10PCS	\$20.00	
9 FRT BUMPER INNER SPONGE ?	1 PC	\$85.00	
10 FRT BUMPER REINFORCEMENT ?	1 PC	\$155.00	
11 FRT BUMPER LOWER GRILLE ?	1 PC	\$105.00	
12 FOG LAMP GARNISH ?	2PCS	\$40.00	
13 FOG LAMP ?	2PCS	TBC	
14 HEADLAMP ✓ CUT	2PCS	\$700.00	
15 HEADLAMP SUPPORT PANEL ?	1 PC	\$350.00	
16 AIRCON CONDENSER ?	1 PC	\$220.00	
17 RADIATOR ?	1 PC	\$250.00	
18 RADIATOR FAN ASSY ?	1 PC	\$215.00	
19 AIRCON SIDE DEFLECTOR ?	2PCS	\$36.00	
20 HEADLAMP LOWER BRACKET ✓ NEC	2PCS	\$36.00	
		\$3,222.00	
	Add 10%	\$322.20	\$3,544.20

Special Nett

1 FRT NUMBER PLATE ✓ CRA	1 PC	\$40.00	
2 FRT BONNET SEALANT ✓ NEC	1 PC	\$60.00	
			\$100.00

Labour

1 WIRE CHECKING	\$20.00	✓
2 REMOVE & REFIX AIRCON AND GAS	\$100.00	✓
3 LABOUR CHARGE	\$750.00	400
4 SPRAY PAINTING	\$750.00	400
	\$1,620.00	

4 Days
Lumpsum repair
After repair photos
Excess: TBA
Not Authorised

Guo Qiang - LKK

82880282

19/04/2022

Amount Before Excess	\$5,264.20
Less Excess	\$0.00
Amount Before GST	\$5,264.20
Add GST @7%	\$368.49
Total Amount Payable	\$5,632.69