

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

THE WINE GALLERY PTE LTD
32 KALLANG PLACE KALLANG BASIN
SINGAPORE 339160

Contact : 96189581 ,90040708

TP Chiam.
Xiao Chen.

TAX INVOICE

Repair Code : CLM17155

Date in : 14/04/2022

Vehicle Num. : GBH1437B

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR

Chassis/Eng# : JN1MC2E26Z0008594/YD25422608A

Parts and Labour Assesment

Description of part	Qty	Unit Price	695 Amount
CENTER PILLAR LH <i>Dented</i>	1	1386.50	1,386.50
FRONT BUMPER <i>Dented</i>	1	571.90	✓ 571.90
FRONT BUMPER LH FOGLAMP GARNISH <i>Dented</i>	1	120.60	✓ 120.60
FRONT BUMPER SIDE RETAINER L/R <i>Lit Dented</i>	2	181.00	362.00
FRONT GRILLE <i>not in</i>	1	527.30	+ 527.30
FRONT GRILLE 'LOGO' EMBLEM <i>not in</i>	1	64.90	+ 64.90
FRONT LH DOOR <i>Dented</i>	1	1071.40	✓ 1,071.40
FRONT LH DOOR CHECKER <i>not in</i>	1	42.80	+ 42.80
FRONT LH DOOR HINGE LOWER <i>not in Dented</i>	1	58.90	✓ 58.90
FRONT LH DOOR INNER ARCH WEATHER STRIP <i>not in</i>	1	176.10	+ 176.10
FRONT LH DOOR INNER TRIM BOARD <i>Dented</i>	1	504.60	✓ 504.60
FRONT LH DOOR PILLAR <i>Repair</i>	1	1156.20	+ 1,156.20
FRONT LH DOOR WEATHER STRIP <i>Also torn</i>	1	123.90	✓ 123.90
FRONT LH HEADLAMP <i>cut</i>	1	485.30	✓ 485.30
FRONT LH LOWER ARM <i>Bent</i>	1	228.30	✓ 228.30
FRONT LH STEP GARNISH <i>Dented</i>	1	55.90	✓ 55.90
FRONT LH TIE ROD END <i>not in</i>	1	142.00	+ 142.00
FRONT LH WHEEL HUB CAP <i>cut</i>	1	161.30	✓ 161.30

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

THE WINE GALLERY PTE LTD
32 KALLANG PLACE KALLANG BASIN
SINGAPORE 339160

Contact : 96189581 ,90040708

TAX INVOICE

Repair Code : CLM17155

Date in : 14/04/2022

Vehicle Num. : GBH1437B

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR

Chassis/Eng# : JN1MC2E26Z0008594/YD25422608A

REAR LH SLIDING DOOR LOWER HINGE <i>HEM</i>	1	134.50	<i>+</i>	134.50
ROCKER PANEL LH <i>Regis</i>	1	325.60	<i>+</i>	325.60
Subtotal before discount				7,700.00
Percentage discount 10%				770.00
Sub-total 1				6,930.00
CENTER PILLAR LH 3D STICKER <i>HEM</i>	1	250.00	<i>180</i>	250.00
FRONT BUMPER CLIPS - SET <i>HEM</i>	1	80.00	<i>30</i>	80.00
FRONT BUMPER LH FOGLAMP <i>HEM</i>	1	311.80	<i>+</i>	311.80
FRONT GRILLE CLIPS - SET <i>HEM</i>	1	30.00	<i>+</i>	30.00
FRONT LH 195R15C TYRE <i>HEM</i>	1	400.00	<i>+</i>	400.00
FRONT LH DOOR 3D STICKER <i>HEM</i>	1	200.00	<i>80</i>	200.00
FRONT LH DOOR COMPANY STICKER <i>HEM</i>	1	25.00	<i>✓</i>	25.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>HEM</i>	1	50.00	<i>30</i>	50.00
FRONT LH KNUCKLE ARM <i>Demid</i>	1	351.50	<i>✓</i>	351.50
FRONT LH KNUCKLE ARM BEARING <i>HEM</i>	1	231.00	<i>✓</i>	231.00
FRONT LH SHOCK ABSORBER <i>HEM</i>	1	140.50	<i>+</i>	140.50
FRONT LH STABILIZER LINK <i>HEM</i>	1	85.60	<i>+</i>	85.60
FRONT LH STEP GARNISH CLIPS - SET <i>HEM</i>	1	30.00	<i>✓</i>	30.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

THE WINE GALLERY PTE LTD
32 KALLANG PLACE KALLANG BASIN
SINGAPORE 339160

Contact : 96189581 ,90040708

TAX INVOICE

Repair Code : CLM17155

Date in : 14/04/2022

Vehicle Num. : GBH1437B

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR

Chassis/Eng# : JN1MC2E26Z0008594/YD25422608A

FRONT LH WHEEL RIM <i>NM</i>	<i>2682.50</i>	1	267.50	+	267.50
REAR LH FENDER 3D STICKER <i>NM</i>		1	600.00	+	600.00
REAR LH SLIDING DOOR <i>Dented.</i>	<i>2414.25</i>	1	1325.00	✓	1,325.00
REAR LH SLIDING DOOR 3D STICKER <i>NM</i>		1	600.00	400.	600.00
Subtotal before discount					4,977.90
Percentage discount 0%					0.00
Sub-total 2					4,977.90
Parts-total					11,907.90

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.
- To road test driving, check and resetting wheel alignments system.
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

	30.	80.00
	220	350.00
	80	100.00
	80	160.00
	900	1,400.00
	1000	1,300.00
	60	120.00
		3,510.00
2370		15,417.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in original state
- Parts prices are subject to confirmation page 3
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian L
L/S 18/04/22
08 Days.
Total: 866.54
L/S: 6.9K