


Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721
 Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: admin@fulcoautocare.com

Make/Model: KIA OPTIMA K5
 Engine/Chassis No.: KNAGU411MG5034612
 Date of accident:
 Damaged area: O/S Front

Date: 28/04/2022
 Claim Type: TP
 VRN: SLE3777D



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet	1	\$ 1,583.00	\$ 1,583.00
2	Bonnet lock	1	\$ 139.00	\$ 139.00
3	Bonnet bottom lock assy	1	\$ 58.00	\$ 58.00
4	Bonnet lock sensor	1	\$ 139.00	\$ 139.00
5	Front fender o/s	1	\$ 920.00	\$ 920.00
6	Front fender cowling o/s	1	\$ 189.00	\$ 189.00
7	Headlamp o/s	1	\$ 2,996.00	\$ 2,996.00
8	Headlamp lower bracket o/s	1	\$ 168.00	\$ 168.00
9	Front bumper	1	\$ 1,286.00	\$ 1,286.00
10	Front bumper tow cover	1	\$ 45.00	\$ 45.00
11	Front bumper "KIA" emblem	1	\$ 76.00	\$ 76.00
12	Front bumper side retainer	2	\$ 48.00	\$ 96.00
13	Front bumper bracket	2	\$ 44.00	\$ 88.00
14	Front bumper grille	1	\$ 457.00	\$ 457.00
15	Front bumper grille chrome trim	1	\$ 289.00	\$ 289.00
16	Front bumper lower grille	1	\$ 394.00	\$ 394.00
17	Front bumper side chrome o/s	1	\$ 293.00	\$ 293.00
18	Washer nozzle o/s	1	\$ 412.00	\$ 412.00
19	Washer nozzle cover o/s	1	\$ 72.00	\$ 72.00
20	Washer nozzle bracket o/s	1	\$ 48.00	\$ 48.00
21	Front bumper sponge	1	\$ 218.00	\$ 218.00
22	Front bumper reinforcement	1	\$ 689.00	\$ 689.00
23	Engine under cowling	1	\$ 280.00	\$ 280.00
24	Front bumper sensor harness	1	\$ 521.00	\$ 521.00
25	Washer tank	1	\$ 187.00	\$ 187.00
26	Washer tank motor	1	\$ 213.00	\$ 213.00
27	Front support frame	1	\$ 995.00	\$ 995.00
			Subtotal	\$ 12,851.00
			List discount	10.00%
			Total	\$ 11,565.90

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet insulator clips	10	\$ 5.50	\$ 55.00
2	Front fender cowling clips o/s	8	\$ 5.50	\$ 44.00
3	Front bumper clips	12	\$ 5.50	\$ 66.00
4	Engine under cowling clips	8	\$ 5.50	\$ 44.00
5	Radiator coolant	1	\$ 60.00	\$ 60.00
6	Front bumper sensor	2	\$ 250.00	\$ 500.00
7	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 819.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and refit radiator to facilitate repair. To perform pressure test and check cooling system functionality.	0.75	\$ 150.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,500.00

Estimate Grand Total	\$ 14,884.90
-----------------------------	---------------------