

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationale Des Experts En Automobile				
11	NDIA INTERNATIO	ONAL INSURANCE PL	Ref:	CS/SGK22003489/Aqy3e2		
	4 CECIL STREET 05-02 IOB BUILDI	NG SINGAPORE 049711	Date:	28/07/2022		
			Code:	III2		
1.	Policy Particulars :- THIRD PARTY CLAIM					
lı	nsured Veh.	CLEAN SOLUTION P L	Veh. Inspected	SJX 7555A		
P	Policy No.	SGK: 6009696/HYL	Coverage (\$)	0.00		
C	Claim No.	III: LPL2022D0002126	Excess (\$)	0.00		
Δ	Assign From	HO YEOW LIANG	Assign Date	14/04/2022		
2. Vehicle Particulars & Condition						
N	/lake & Model	MERCEDES BENZ C200	c.c	1991		
E	ngine No.	HIDDEN	Year of Reg.	2015		
C	Chassis No.	WDD2050422R037707	Colour	BLACK		
C	Odometer	150284 KM	Steering	IN ORDER		
Е	Brakes	IN ORDER	Modification	SPORTS RIM		
G	General	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
R	R/H Front Tyre	245/40 R18	ROYAL PERFORMANCE	6 mm		
L	/H Front Tyre	245/40 R18	ROYAL PERFORMANCE	6 mm		
R	R/H Rear Tyre	245/40 R18	ROYAL PERFORMANCE	6 mm		
L	/H Rear Tyre	245/40 R18	ROYAL PERFORMANCE	6 mm		
4.	4. Description of Damages					
Т	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
Δ	Accident Date	08/04/2022	Inspection Date	14/04/2022		
S	Survey held at	GREEN FOREST AUTOMOBILE				
		8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
A B	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
<b>C</b> I-	Estimate Days of Repair					
5b.						