

# GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

SYLLYS AUTO PTE LTD  
8 KAKI BUKIT AVE 4  
# 05-25 PREMIER @ KB  
Singapore 415875

12<sup>th</sup> April 2022

Public Liability,  
Xiao Chen.

WDD2050422R037707

Accident date: 08<sup>th</sup> APRIL 2022

Estimated repair cost for vehicle no: SJX7555A MERCEDES C200 AMG LINE 2015

| S/n | Qty | Items/Nett                                        | U/price  | Amount                  |
|-----|-----|---------------------------------------------------|----------|-------------------------|
| 1   | 1   | Rear bumper <i>Not new</i>                        |          | \$1,445.00 X            |
| 2   | 2   | Rear bumper side bracket <i>Not new</i>           | \$135.20 | \$270.40 X              |
| 3   | 1   | Tail lamp <i>Cracked</i>                          |          | <del>\$852.00</del> 725 |
| 4   | 1   | Rear fender RH <i>Repair</i>                      |          | \$1,954.00 X            |
| 5   | 1   | Rear fender R/H cowlings <i>Not new</i>           |          | \$144.00 X              |
| 6   | 1   | Front R/H door <i>Dented</i>                      |          | \$1,623.00 ✓            |
| 7   | 1   | Front RH door inner lock <i>Dmgd</i>              |          | <del>\$590.00</del> 385 |
| 8   | 1   | front R/H door top moulding <i>Not new</i>        |          | \$168.20 X              |
| 9   | 1   | Front RH door gear motor assy <i>Dmgd</i>         |          | \$852.00 540            |
| 10  | 1   | front R/H door outer handle <i>Not new</i>        |          | \$165.20 X              |
| 11  | 1   | front R/H door glass rubber <i>Not new</i>        |          | \$210.00 X              |
| 12  | 1   | front R/H door top moulding rubber <i>Not new</i> |          | \$155.20 X              |
| 13  | 1   | Front R/H door inner rubber <i>Not new</i>        |          | \$218.20 ✓              |
| 14  | 1   | front R/H door inner trim board <i>Not new</i>    |          | \$1,480.00 X            |
| 15  | 1   | Rear RH door <i>Dented</i>                        |          | \$1,623.00 ✓            |
| 16  | 1   | rear RH outer handle <i>Not new</i>               |          | \$165.20 X              |
| 17  | 1   | rear RH door top moulding <i>Not new</i>          |          | \$168.20 X              |
| 18  | 1   | rear RH door inner rubber <i>Not new</i>          |          | \$215.20 ✓              |
| 19  | 1   | Rear R/H knocking arm <i>Not new</i>              |          | \$854.00 X              |
| 20  | 1   | Rear R/H wheel bearing <i>Not new</i>             |          | \$226.00 X              |
| 21  | 1   | Rear R/H lower arm <i>Not new</i>                 |          | \$472.00 X              |
| 22  | 1   | RAER RH Rim <i>Not new</i>                        |          | \$750.00 X              |
| 23  | 1   | Rear RH Tyre <i>Not new</i>                       |          | \$550.00 X              |

Subtotal :- \$15,150.80

## Labour charges

To remove & re-fix rear undercarriage \$380.00 X

To check wheel alignment \$120.00 X

To remove & re-fix cushion \$150.00 ✓

tuff Kote \$150.00 60

Spray painting \$1,200.00 700

Panel beating \$1,200.00 600

Subtotal :- \$3,200.00

Total :- \$18,350.80

KKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after: spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5329  
4796.10

Total: 6306.10  
H/S: 5K  
04 Days