4314-32-C6Z5

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	VEHICLE
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	507D
Vehicle No.:	SMX3677Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	LEB7112234
Chassis No.:	GP72009792
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$23,626.00
Original Registration Date:	08 Jan 2021
First Registration Date:	08 Jan 2021
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$10,077.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2031
PARF Rebate Amount: Intended COE Rebate Details	\$7,557.00
COE Expiry Date:	07 Jan 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,012.00
COE Rebate Amount:	\$36,009.00
Total Rebate Amount:	\$43,566.00

The information contained herein is correct as at 12 Apr 2022



CarTimes Autolution Pte Ltd 160 Sin Ming Drive AutoCity #02-04 Singapore 575722 Tel: 6471 5111 Email: claims@cartimes.com.sg

VEHICLE NO: SMX3677Y CHASSIS NO: GP7-2009792 Not Norhorise USry & Rewney Har Paint 14days

MODEL: HONDA SHUTTLE

DESCRIPTION	REPAIRER'S
PARTS (LIST ITEMS)	ESTIMATE(S\$)
REAR BUMPER	To \$ 1,210,00
	\$ 1,210.00
REAR BUMPER RETAINER RHS	\$ 40.00
REAR BUMPER REFLECTOR	Miy \$ 70.00
REAR BUMPER COVER RHS TAILGATE	\$ 40.00
TAILGATE TAILGATE LAMP LHS	\$ 1,000.00
TAILGATE LAMP LHS	\$ 1 400.00
	Bu\$ 400.00
TAILGATE WEATHERSTRIP TAILGATE LOCK ASSY	Dillas 120.00
TAILGATE LOCK ASSY TAILGATE INNER TRIM	Tu \$ 180.00
	Bu \$ 210.00
TAIL GATE CENTRE GARNISH (CHROME) HONDA EMBLEM	Mzm \$ 480.00
SHUTTLE EMBLEM	\$ Mec 50.00
REAR WINDSCREEN	% \$ 60.00
	Shorters \$ 60.00 1,240.00
REAR WINDSCREEN MOULDING REAR WIPER MOTOR	\$ 100.00
REAR WIPER MOTOR	\$ 380.00
	\$ 80.00
REAR SPOILER WING	\$ 1,220.00
HIRD BRAKE LAMP	\$ 230.00
AIL LAMP LHS	\$ 410.00
AIL LAMP RHS	32 \$ 410.00
AIL LAMP PANEL RHS	\$ 1/2 200.00
ND PANEL	\$ Pg 460.00
ND PANEL TOP GARNISH	\$ 110.00
PARE TYRE PANEL	\$ 990.00
ARE TYRE TOP COVER	\$ 460.00
ARE TYRE TOOL BOX SPONGE	
AR FRAME STIFFENER RHS	
AR FENDER LHS	
AR FENDER INNER SHIELD RHS	By \$ 910.00
AR FENDER PILLAR TRIM (UPPER)	100.00
AD LEMPELY LIFEWING (OLLETA)	\$ 220.00

	REAR FENDER INNER TRIM LHS
1	REAR WHEELHOUSE PANEL LHS
	REAR QUARTER GLASS RHS
	REAR QUARTER GLASS MOULDING RHS
	REAR DOOR LHS
l	REAR SIDE FRAME RHS (UPPER)
F	ROOF
F	ROOF LINING
F	ROOF GARNISH RHS
F	REAR SEAT BELT ASSY RHS
F	REAR SPORTS RIM RHS
F	ROOF GARNISH LHS
F	REAR BUMPER SPONGE RHS
S	SPARE TYRE STORAGE COVER
S	PARE TYRE STORAGE COVER DOOR
T	AILGATE ABSORBER
Т	AILGATE HINGE LHS
T.	AILGATE HINGE RHS
R	EAR FENDER INNER TRIM RHS (UPPER)
	EAR FENDER AIR GUIDE RHS
R	EAR WHEELHOUSE PANEL UPPER
	OOF
•	

_			
Bu Br Phothers	\$	360.00	_
OI By	\$	680.00	<u></u>
1 nothers	\$	500.00	_
Men	\$	200.00	_
n	\$	910.00	×
n	\$	960.00	X
K	\$	1,080.00	X
Sm	\$	1,130.00	x
Pn	\$	150.00	X
	\$	600.00	7
Per	\$	500.00	250/n
Put In CM	\$	150.00	X
cm	\$	80.00	-
	\$	300.00	7
	\$	100.00	7
	\$	200.00	ファファファ
	\$	80.00	7
	\$	80.00	7
su	\$	120.00	^
cm	\$	80.00	-
	\$	250.00	?
K	\$	1,080.00	X
	•	.,	
	\$	21,750.00	
20%	\$	4,350.00	
	\$	17,400.00	

SPECIAL NETT ITEMS REAR SENSORS REAR BUMPER CLIPS 1 SET DASH CAMERA CARPLATE W/HOLDER CEREMIC COATING	Total	Mis Re Si (Bill)	\$ \$ \$ \$ \$ \$ \$ \$ \$	60.00 300.00 60.00 600.00	レメン
	Total	-	\$	1,220.00	_
	TOTAL PA	RTS	\$	18,620.00	

SI	DESCRIPTION		
1	LABOUR	EPAIRER'S	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 71MATE (S\$) 2,500.00	cod
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ <i>/€</i> ,200.00	001
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	201
4	To provide anti-rust treatment on affected areas	\$ 100.00	_
5	Remove and refit rear windscreen	\$ 150.00	12d
6	Remove and refit rear quarter glass	\$ 150.00	601
7	Remove and refit roof lining	\$ 200.00)
8	Remove and refit rear upholstery	\$ 300.00	154
9	Transfer tailgate parts	\$ 150.00	601
	Labour Total :	\$ 5,850.00	
	TOTAL (PARTS & LABOUR):	\$ 24,470.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

1. Please report correctly the details of the accident to speed up the claims process

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident**

Additional Location Information Country/State of Loss

11/04/2022 17:45 (SGT) 08/04/2022 00:30 (SGT) TPE, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMX3677Y

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No **Email Address**

Mobile Phone No Alternative Phone No. TZE SWEE POH (XU RUIBAO) SXXXX507D

No

claims@cartimes.com.sq (Phone) +65-98223311 +65-98223311

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission

CC

Honda Shuttle

Private use

No - Claiming third party

Private car Auto

1496

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy **Policy Number**

Cover Note Number

Liberty Insurance Pte Ltd Comprehensive

No

SD22V04233/VPL/R00

DRIVER

Name of Driver NRIC No

TZE SWEE POH (XU RUIBAO) SXXXX507D



PAccident report SC1E224B0003

Refer to Police Report.	
A MANAGEMENT CONTROL OF THE CONTROL	2000
4.0000000000000000000000000000000000000	
	A STATE OF THE STA
	and the second s
um coperado en Nocembro de Acono de Carlos de	
	and the property of the second
	1997 J. S. Waller & P. W. Waller & W. W. Waller & W.
11.2	

Declaration

Term

We declare the foregoing particulars are true in every respect.

Folicyholder's Signature / Date &

Driver's Signature (# driver is not the policyholder) / Date 8 Time

Witnessed by Reporting Centre